

# Rapport 8D

Généré Par: Eveline Rochegude Généré Le: 13 Jul 2011

## I. COMPLAINT INFORMATION / IDENTIFICATION DE LA RECLAMATION

Date De La Réclamation	11 Jul 2011					
Nom correspondant commercial	Benoit Garnier	Sales Office (Bureau Commercial)	Valence			
Téléphone	+33 (0)4 75 44 80 00	No. Fax	-			
Email	benoit.garnier@scapa.com					
Référence réclamation client						
Nom Du Client	Cad					
Numero De Client SAP	107143	N° Commande Client				
Rfrence Article Client						
,	s Sur La Réclamation					
(a) Numéro De Facture SAP	9200282724	Date De Facture	29 Nov 2010			
- Matériel	112997	Lot				
	Description Produit					
	0485 Ambre 0.4mm x 25mm x 30m					
2) Description Du Problème Identifié Par Le Client						
The product liquefies as you can see it on the sample of cover sent by the customer.						
The product is used to join covers plastic, beforehand cleaning with IPA.						
Covers are hung from several meters high in stores (thus inside), no direct exposure to ultraviolet rays.						
It is not the first time that happens and the customer was obliged to begin again to join the covers (total surface 220m ²)						
Actions demandées au clie	nt					

3) Actions Conservatoires Sur Le Process						

# Echantillons/Photos Reçus No Date Responsable Processus Eveline Rochegude Responsable Action Réclamation justifiée? No Retour marchandise Destruction marchandise

### 1) Analyse

The customer is complaining in respect of Scapa 0485 Amber 0.4mm x 25mm x 30m (item 112997), due to "The product liquefies as you can see it on the sample of cover sent by the customer. The product is used to join covers plastic, beforehand cleaning with IPA"

As part of the customers manufacturing activity, it is understood that the 0485 product is used in an environment where it is exposed to a solvent (IPA, iso propyl alcohol) and its fumes.

Scapa would not recommend using 0485 in any environment where this product would be exposed to solvent fumes. This is stated on the Scapa Technical Data Sheet for this product: "The product must be protected from dust, heat, moisture, direct sunlight and solvent fumes". As Scapa 0485 is a rubber-resin adhesive strip, any exposure to solvent and or its fumes would lead to softening or even dissolution.

Therefore, this complaint is deemed as not valid.

Auteur	Philip Ward	Date	13 Jul 2011			
2) Causes						
Auteur		Date				
3) Solutions Possibles						
Auteur		Date				
4) Mise En Place Actions Correctives Permanentes						
Auteur		Date				
Date Estimée		Date De Mise En Place				
Date De Validation						

# 5) Validation Des Actions Correctives Auteur Date 6) Actions Préventives Date Auteur Date Estimée Date De Mise En Place Date De Validation 7) Mise à Jour Documentation (a) MSR Commenté? No Référence Date (b) Révision logigrammes/plans de surveillance/instructions de fabrication et de contrôle Commenté? No Référence Date (c) Révision AMDEC Commenté? No Référence Date (d) Spécification client Commenté? No Référence Date

8) Félicitations à Toute L'équipe