



Report 8D

Generated By: Seb Houle Generated On: 21 Jun 2011

I. COMPLAINT INFORMATION

Origination Date	08 Jun 2011						
Sales Name	Jim Shauck	Sales Office	Windsor				
Telephone	-	Fax Number	-				
Email	Jim.Shauck@scapa.com						
Customer Complaint Ref							
Customer Name	Vermed Inc.						
SAP Customer Number	128106	Customer Order N°					
Customer Part Number							
1) Invoices And Items	s On Complaint						
(a) SAP Invoice Number	9700038831	Invoice Date	17 May 2011				
- Material	160479	Batch					
	Material Description						
	RX1372P 1/16PE FOAM/[A]/88# 5IN X 600F						
2) Problem Description							
Customer found 3 rolls of foam with 5-6 splices in them. Customer spec states a maximum pf 3 splices per roll.							
Actions Requested From The Customer							
Root Cause and corrective action.							
3) Containment Actions							

II. EVALUATION AND ACTION

Sample/photo Received	Yes								
Date	07 Jun 2011								
Process Owner	Seb Houle								
Team Leader	Seb Houle								
Is Complaint Valid?	Yes	Return The Goods		Dispose The Goods					
Comments									
1) Analysis									
Customer received (at least	t) 3 rolls with excessiv	re splices in them. Specif	icaiton is for a maximum of 3 s	splices per roll,					
however rolls had 5 or 6. Co	ustomer has not yet p	rocessed all rolls in order	·.						
Author	Seb Houle		Date	08 Jun 2011					
2) Root Causes									
Due to high scrap rates on	the run (~18%) slitting	resulted in a high numb	er of splices. The maximum nu	umber of allowable splices					
was not adhered to, as to e	nsure that the order d	id not run short of materi	al.						
Author	Seb Houle		Date	08 Jun 2011					
3) Possible Solutions									
-Update slitting specification complained."	n to add comment to t	he slitting specification no	ote: "3 Splices maximum, cust	omer has					
-Additionally, create a defec	ct folder for slitting and	d begin to populate.							
Author	Seb Houle		Date	21 Jun 2011					
4) Implemented Perm Corrective Actions									
 Added comment to the slitting specification note: "3 Splices maximum, customer has complained." Began to populate a new computer folder that is accessible to all slitting operators (at their work station) with digital photos of defects. A digital picture of the roll with too many splices, noting the discrepancy of spices, was placed in the folder. 									
Author	Seb Houle		Date	21 Jun 2011					
Estimated Date			Implementation Date						
Validation Date									

5) Corrective Actions Validation

Inspected next production run for excessive splices and didn't find any discrepencies.							
Author	Seb Houle	Date	21 Jun 2011				
6) Preventive Actions							
Author		Date					
Estimated Date		Implementation Date					
Validation Date							
7) Review Of Documentation							
(a) MSR							
Reviewed?	No						
Reference		Date					
(b) Flow chart, control plan, work inspection instructions							
Reviewed?	No						
Reference		Date					
(c) FMEA							
Reviewed?	No						
Reference		Date					
(d) Customer specification							
Reviewed?	No						
Reference		Date					

8) Congratulate The Team