



Health and Safety Syracuse Report

Generated By: Jason Matthews Generated On: 08/04/2010 - March


LTA




Accidents




LTD




Reportable



Safety Opportunities



DACR



Dangerous Occurrences Reported in Month

- # Description of Dangerous Occurrence
- 1 Grease, oil and resin spilled under extruder carriage causing slip hazard
- 2 Night winder operator not wearing hearing protection
- 3 Extruder catwalk cluttered with old belnder, extension cord and cleaning bucket
- # Remedial Action
- 1 Instructed crews to clean and an monitor
- 2 Asked operator to get hearing protection and wear it
- 3 Instructed crews to clean and an monitor
- # Key H&S Initiatives: This is a listing of the key initiatives underway in your site at this time. These are the same initiatives that will transfer to your Site Pack. The should be new initiatives and not routine items.
- 1 Replace second rear dock door bumper with more durable one. This new one is cracked.
- 2 Secure the banister railing next to stairs at shipping entrance.
- 3 Annual OSHA training being scheduled for first quarter of FY11