



Bericht 8D

Generiert Von: Wolfgang Rupp Generiert: 24 Oct 2011

I. REKLAMATIONSDATEN

Kreiert	14 Sep 2011				
Verkäufer Name	Thomas Drews	Verkaufs Büro	Mannheim		
Telefon		Faxnummer			
Email	thomas.drews@scapa.com				
Kunden reklamations ref					
Kundenname	FFT Handelsgesellschaft				
SAP Kundennummer	110855	Kunden Bestellnummer			
Teile Nr Des Kunden					
1) Rechnungen Und	Artikel Dieser Reklamation				
(a) SAP Rechnungsnummer	9350063345	Rechnungsdatum	30 Aug 2011		
- Material	138652	Batch	15587-1		
	Materialbeschreibung 3159 Silber 1220mm x 1400m Neutral				
2) Problembeschreibung					
Jumbo has stripes and wrinkles the same problem as complaint 100903!!!!!					
Aktion vom Kunde gefordert					

3) Sofort Maßnahmen Am Process

II. AUSWERTUNG UND AKTIONEN

Muster/Photo Erhalten	No					
Datum						
Prozess Besitzer	Wolfgang Rupp					
Team Leiter	pbarrow					
Ist Reklamation berechtigt?	Yes Material retournieren	N	Material vernichten			
Bemerkungen						
1) Analyse						
It appears that the custome	er has undergone some form of delamination v	vith this product.				
As seen from this photograph the material has ripped out when they have been trying to convert.						
Autor	Paul Barrow	Datum	21 Oct 2011			
2) Ursache						
The root cause has not been fully determined. But could be attributed to either an issues with a stoppage during production or a raw material issue.						
Autor	Paul Barrow	Datum	21 Oct 2011			
3) Mögliche Lösungen						
Review the resin feed start up / shut down procedure. Investigate film supply and QC records						
Autor	Paul Barrow	Datum	21 Oct 2011			
4) Einführung Der Korrektur-Massnahmen						
Review of records, indicates there was an issue with the shut down and start up of the resin feeders. The resin feeders over supplied and created a high tack area in the jumbo.						
The resin feeder system has been reviewed and programed to eliminate operator intervention.						
Autor	Paul Barrow	Datum	21 Oct 2011			
Geschtztes Plannungsdatum	21 Oct 2011	Implementierungs Datum	21 Oct 2011			
Validierungsdatum	21 Oct 2011					
5) Korrekturmaßnahmen Validierung						
Review of records, indicates there was an issue with the shut down and start up of the resin feeders. The resin feeders over						

Review of records, indicates there was an issue with the shut down and start up of the resin feeders. The resin feeders over supplied and created a high tack area in the jumbo.

The resin feeder system has been reviewed and programed to eliminate operator intervention.

Monitor situation with check sheets						
Autor	Paul Barrow	Datum	21 Oct 2011			
6) Vorbeugende Massnahmen						
Review of records, indicates there was an issue with the shut down and start up of the resin feeders. The resin feeders over						
supplied and created a high	n tack area in the jumbo.					
The resin feeder system has been reviewed and programed to eliminate operator intervention.						
Monitor situation with check	k sheets					
Autor	Paul Barrow	Datum	21 Oct 2011			
Geschtztes Plannungsdatum	21 Oct 2011	Implementierungs Datum	21 Oct 2011			
Validierungsdatum	21 Oct 2011					
7) Überprüfung Der Dokumentation						
(a) MSR						
Zutreffend?	No					
Referenz		Datum				
(b) Flussdiagramm, Arbeitsanweisungen						
Zutreffend?	No					
Referenz		Datum				
(c) FMEA						
Zutreffend?	No					
Referenz		Datum				
(d) Kunde Spezifikation						
Zutreffend?	No					

Datum

8) Gratuliere Dem Team

Referenz