



Report 8D

Generated By: José Gonzalez Generated On: 08 Sep 2011

I. COMPLAINT INFORMATION

Origination Date	04 Aug 2011					
Sales Name	Mauro Granaglia	Sales Office				
Telephone		Fax Number				
Email						
Customer Complaint Ref						
Customer Name	Cintubex S.L.					
SAP Customer Number	112971	Customer Order N°	287/11			
Customer Part Number	MARKAN33RO50					
1) Invoices And Items	s On Complaint					
(a) SAP Invoice Number	9200293524	Invoice Date	13 Apr 2011			
- Material	103584	Batch				
	Material Description					
	2721 Rojo 50mm x 33m Neutro					
2) Problem Description						
Rolls damaged.						
Actions Requested From The Customer						
3) Containment Actions						

II. EVALUATION AND ACTION

Sample/photo Received	No						
Date							
Process Owner	Claudio Mutti						
Team Leader	cmutti						
Is Complaint Valid?	Yes Return The Goods	No	Dispose The Goods	Yes			
Comments							
1) Analysis							
Based of the information received the rolls are telescoped This issue could happens spottly due to the interaction between PVC							
film and adhesive. From technical point of view the product is ok (adhesion) but we know there are some difficult to use. Telescoping is the result of the interaction of several causes related to the elastic memory of the calendered soft pvc. Scapa is already using the best of the known self-adhesive tapes technology to avoid this undesired effect. The defect is not detectable on logs and the 100% of control on produced rolls is not possible, due also to negative cost effects A very small percentage of rolls, under stressed environmental conditions (e.g. during transport, stocking etc) can telescope.							
Author	Claudio Mutti	Date	05 Aug 2011				
2) Root Causes							
Telescoping is the result of the interaction of several causes related to the elastic memory of the calendered soft pvc. Scapa is already using the best of the known self-adhesive tapes technology to avoid this undesired effect. The defect is not detectable on logs and the 100% of control on produced rolls is not possible, due also to negative cost effects A very small percentage of rolls, under stressed environmental conditions (e.g. during transport, stocking etc) can telescope.							
Author	Claudio Mutti	Date	05 Aug 2011				
3) Possible Solutions							
Author		Date					
4) Implemented Perm Corrective Actions							
Check of 100 % batches of produced adhesive - Statistic test of accelerate simulation of environmental stress on 100% of							
produced pvc tapes batches. The actions are in place since year 2003							
Author	Claudio Mutti	Date	05 Aug 2011				
Estimated Date	05 Aug 2011	Implementation Date	05 Aug 2011				
Validation Date	05 Aug 2011						

5) Corrective Actions Validation Author Date 6) Preventive Actions Author Date **Estimated Date** Implementation Date Validation Date 7) Review Of Documentation (a) MSR Reviewed? No Reference Date (b) Flow chart, control plan, work inspection instructions Reviewed? No Reference Date (c) FMEA Reviewed? No Reference Date (d) Customer specification Reviewed? No Reference Date

8) Congratulate The Team