



Report 8D

Generated By: Doug Matthews Generated On: 19 Aug 2011

I. COMPLAINT INFORMATION

Origination Date	06 Jun 2011						
Sales Name	Jim Shauck	Sales Office	Windsor				
Telephone	-	Fax Number	-				
Email	Jim.Shauck@scapa.com						
Customer Complaint Ref							
Customer Name	Majilite Corporation						
SAP Customer Number	127457	Customer Order N°					
Customer Part Number							
1) Invoices And Items On Complaint							
(a) SAP Invoice Number	9700038226	Invoice Date	28 Apr 2011				
- Material	159876	Batch	2006981				
	Material Description						
	61" Medical Liner						
2) Problem Description							
-Customer complained of a paper defect repeating 61" approx 17-19" from one side. Defect is a depression in paper on the PP							
coated side. They reported the defect in MR 1,2,4,5,16, and 17.							
Actions Requested From The Customer							
Supply additional information.							
3) Containment Actions							

Customer contained product with defect at site and processed material deemed acceptable.

II. EVALUATION AND ACTION

Sample/photo Received	No							
Date	19 Aug 2011							
Process Owner	Doug Matthews							
Team Leader	Imurphy							
Is Complaint Valid?	Yes Return The Goods	Yes	Dispose The Goods	No				
Comments								
1) Analysis								
	ressions in the paper. Upon review of our fect the supplier calls "SCABS".	retains we found the same depre	essions in several of the					
Author	Liz Murphy	Date	09 Jun 2011					
2) Root Causes								
This is a paper defect caused during the paper manufacturing process. There are low spots in the paper caused by debri sticking to one of the drums on the paper manufacturing line.								
Author	Liz Murphy	Date	09 Jun 2011					
3) Possible Solutions								
3) Possible Solutions								
3) Possible Solutions								
Possible Solutions Author		Date						
•		Date						
Author 4) Implemented Perm			pection prior to					
Author 4) Implemented Perm (Internal) - Added a quality processing. (External) - Our manufacture	n Corrective Actions	All raw base paper requires inspose of the scabs involved on comp		of				
Author 4) Implemented Perm (Internal) - Added a quality processing. (External) - Our manufactur starch on the calender stace	n Corrective Actions inspection step to manufacturing process. ing team has determined that the root cau	All raw base paper requires inspose of the scabs involved on compons taken are:	olaint SC20167 was a spot	of				
Author 4) Implemented Perm (Internal) - Added a quality processing. (External) - Our manufactur starch on the calender stac A) Shared the defect sample	n Corrective Actions inspection step to manufacturing process. ing team has determined that the root cau k of the paper machine. The corrective act	All raw base paper requires inspose of the scabs involved on compons taken are:	plaint SC20167 was a spot e problem.	of				
Author 4) Implemented Perm (Internal) - Added a quality processing. (External) - Our manufactur starch on the calender stac A) Shared the defect sampl B) Reviewed and reinforced	n Corrective Actions inspection step to manufacturing process. ing team has determined that the root cau k of the paper machine. The corrective act	All raw base paper requires inspective of the scabs involved on compons taken are: Intended to change starch filters	plaint SC20167 was a spot e problem.	of				
Author 4) Implemented Perm (Internal) - Added a quality processing. (External) - Our manufactur starch on the calender stac A) Shared the defect sampl B) Reviewed and reinforced C) Reviewed and reinforced	in Corrective Actions inspection step to manufacturing process. ing team has determined that the root cau k of the paper machine. The corrective act es with all of the operators involved to height our procedure to check for starch cleanling dour procedure to inspect caliper strips act dour procedure to isolate and contain any	All raw base paper requires inspace of the scabs involved on compons taken are: The appropriate the scabs involved on compons taken are: The appropriate the scabs involved on compons taken are: The appropriate the scabs involved on compons taken are: The appropriate the scabs involved on compons taken are: The appropriate the scabs involved on compons taken are: The appropriate the scabs involved on compons taken are:	plaint SC20167 was a spot e problem. as needed.					

Author	Doug Matthews	Date	25 Jul 2011				
Estimated Date	09 Jun 2011	Implementation Date	17 Jun 2011				
Validation Date	30 Jun 2011						
5) Corrective Actions	· Validation						
Internal) - Raw material inspection prior to run revealed a greater confidence in the material being run. It also identified a ew concern areas we were able to monitor and evaluate.							
(External) - Paper inspection prior to runs since the scab was detected and corrected at Finch have been clean. Every paper roll for Majilite is inspected and the operators are familiar with the defect and how to look for it. No issues since the run with this defect.							
Author	Doug Matthews	Date	19 Aug 2011				
6) Preventive Actions							
Future runs will have the paper inspected prior to extrusion. With the operator familiarity with the scabs, we have a high confidence level in our ability to detect and screen any scabs in the paper.							
Author	Doug Matthews	Date	19 Aug 2011				
Estimated Date		Implementation Date					
Validation Date							
7) Review Of Documentation							
(a) MSR							
Reviewed?	No						
Reference		Date					
(b) Flow chart, control plan, work inspection instructions							
Reviewed?	Yes						
Reference	Printed on the order packet	Date	19 Aug 2011				
(c) FMEA							
Reviewed?	No						
Reference		Date					
(d) Customer specification							
Reviewed?	No						

Date

8) Congratulate The Team

Reference