





Report 8D

Generated By: Kerry Sykes Generated On: 14 Oct 2011

I. COMPLAINT INFORMATION

Origination Date	26 Sep 2011		
Sales Name	Andrew Sampson	Sales Office	Ashton
Telephone	+44 (0)161 301 7400	Fax Number	+44 (0)161 301 7445
Email	andrew.sampson@scapa.com		
Customer Complaint Ref			
Customer Name	Flowstrip Limited		
SAP Customer Number	100009	Customer Order N°	
Customer Part Number			
1) Invoices And Items			
(a) SAP Invoice Number	9100247457	Invoice Date	24 Aug 2011
- Material	114404	Batch	
	Material Description		
	3120 Silver 1230mm x 750m Plain		

2) Problem Description

Problems encountered with:
3120 silver
BN 15595/1
Order 15087
Delivery note 81063132
(3120 silver BN 15598/1), there is once again 'BON' marked material present – why?
Differential tension, creasing/folds, badly marked surface

Actions	Requested	From	The	Customer

3) Containment Actions

II. EVALUATION AND ACTION

Sample/photo Received	Yes				
Date	26 Sep 2011				
Process Owner	II-soo Choi				
Team Leader	ISChoi				
Is Complaint Valid?	Yes Return The Goods]	Dispose The Goods		
Comments					
1) Analysis					
"BON" printed tape was de	tected in cloth fabric.				
Plastic (PE) inclusion.					
Author	Il-soo Choi	Date	27 Sep 2011		
2) Root Causes					
"BON" tape					
"BON" printed tape was de	tected in cloth fabric.				
Fabric supplier used an ina	appropriate splicing tape.				
Plastic (PE) inclusion					
Insufficient temperature sta	andard management.				
Temperature of cooling roll	er in PE coating line, is higher than standard.				
A scrap of PE was sticking	to cooling roller and got into the product.				
Author	II-soo Choi	Date	12 Oct 2011		
3) Possible Solutions	3				
Author		Date			
4) Implemented Perm Corrective Actions					
We informed our cloth fabric supplier that do not use "BON" printed tape as splicing tape and they'll use a suitable tape.					
Line worker and QC inspector will conduct incoming inspection and in-process inspection more closely.					
Cooling system has been improved. Temperature of cooling roller is in the control of worker and inspector.					
remperature of cooling roll	er is in the control of worker and inspector.				
STK will compensate for th	e defective goods.				
Author	Il-soo Choi	Date	11 Oct 2011		

Estimated Date		Implementation Date	13 Oct 2011			
Validation Date	14 Oct 2011					
5) Corrective Actions Validation						
Fabric supplier accepted or	ur complaint offer, they will use other transpare	ent tape as splicing tape.				
Coolant's temperature is lo	wer than standard.					
Author	II-soo Choi	Date	14 Oct 2011			
6) Preventive Actions	3					
Author		Date				
Estimated Date		Implementation Date				
Validation Date						
7) Review Of Documentation						
(a) MSR						
Reviewed?	No					
Reference		Date				
(b) Flow chart, control plan, work inspection instructions						
Reviewed?	No					
Reference		Date				
(c) FMEA						
Reviewed?	No					
Reference		Date				
(d) Customer specification						
Reviewed?	No					
Reference		Date				

8) Congratulate The Team