



Health and Safety Carlstadt Report

Generated By: Jason Matthews Generated On: 03/12/2009 - November


LTA




Accidents




LTD




Reportable



Safety Opportunities



DACR



Dangerous Occurances

- Skids stored on back loading dock stored greater than 6 feet high
- Electrical panel in the slitting department was blocked by empty boxes.
- Electrical panel on the G&A was observed to be unlocked.
- A skid located on the top rack carrying one roll of 290LP backing was severly damaged.
- A black drum was being used to capture rain water leaking through the ceiling in the small mix room. It is not easy to tell the drum did not contain hazardous material without smelling the liquid.