





Report 8D

Generated By: Chris Bryson Generated On: 15 Jun 2011

I. COMPLAINT INFORMATION

Origination Date	10 Jun 2011		
Sales Name	Chris Martin	Sales Office	Windsor
Telephone	+1 803 749 1130	Fax Number	-
Email	Chris.Martin@scapa.com		
Customer Complaint Ref			
Customer Name	Corning Cable Systems Tcp		
SAP Customer Number	126965	Customer Order N°	
Customer Part Number			

1) Invoices And Items On Complaint

2) Problem Description

Material was damaged in transit.

This is consignment material so there is no invoice associated with it. The material being returned to us will be deducted from there on hand inventory, inspected and shipped back to them.

The following is what is being returned to us.

164212 (3 boxes) 334,800m or 8370 m2

164213 (1 box) 93,600m or 2808 m2

164214 (3 boxes) 241,200m or 8442 m2

164216 (1 box) 61,200m or 2754 m2

Actions Requested From The Customer

We are shrink wrapping the top layer to the bottom layer temporarily to elimainate this issue until we fully implement a new packing procedure for both Corning locations which does not use any cardboard packaging.

3) Containment Actions

The damaged material is being returned to Renfrew for rework. There is no other affected material either at Renfrew or at Corning.

II. EVALUATION AND ACTION

Sample/photo Received	Yes						
Date	10 Jun 2011						
Process Owner	Chris Bryson						
Team Leader	jcbryson						
Is Complaint Valid?	Yes Return The Goods	Yes	Dispose The Goods	No			
Comments							
1) Analysis							
Unsecured top layer of mat	erial shifted during transport and crushed the	edges of the top roll of the bott	om layer of material.				
Author	Chris Bryson	Date	14 Jun 2011				
2) Root Causes							
The top skid not secured to layer.	o the lower skid has made it possible for the t	op skid to shift during transport	and crush the bottom				
Author	Chris Bryson	Date	14 Jun 2011				
3) Possible Solutions							
Change packaging.							
Author		Date					
4) Implemented Perm Corrective Actions							
As an iterim corrective action we are correcting this problem by shrinkwrapping the top layer to the bottom layer.							
Author	Chris Bryson	Date	14 Jun 2011				
Estimated Date	15 Jul 2011	Implementation Date	14 Jun 2011				
Validation Date							
5) Corrective Actions Validation							
As a permanent corrective action we are eliminating the cardboard packaging. Rolls will be stacked in towers and shrunk wrapped							
to the pallet. Samples of the new packaging have been approved by Corning.							
The implementation date of this change will occur by July 15 ,2011.							
Author	Chris Bryson	Date	15 Jun 2011				

6) Preventive Actions

New packaging proposal has been approved by Corning.						
Author	chris bryson	Date	15 Jun 2011			
Estimated Date		Implementation Date	18 Jul 2011			
Validation Date						
7) Povious Of Degumentation						
7) Review Of Documentation						
(a) MSR						
Reviewed?	No					
Reference		Date				
(b) Flow chart, control plan, work inspection instructions						
Reviewed?	No					
Reference		Date				
(c) FMEA						
Reviewed?	No					
Reference		Date				
(d) Customer specification						
Reviewed?	No					
Reference		Date				

8) Congratulate The Team