

100739



Report 8D

Generated By: Paola Baglione Generated On: 27 Sep 2011

I. COMPLAINT INFORMATION

Origination Date	12 Jul 2011					
Sales Name	Teresa Hajec	Sales Office	Mannheim			
Telephone		Fax Number				
Email	teresa.hajec@scapa.com					
Customer Complaint Ref	Complaint 60-11 4970010300					
Customer Name	Sews-Cabind Poland					
SAP Customer Number	104745	Customer Order N°				
Customer Part Number	4970010300					
1) Invoices And Items						
(a) SAP Invoice Number	9301104988	Invoice Date	08 Jun 2011			
- Material	103078	Batch				
	Material Description					
	2702 Black 19mm x 33m Scapa Towerpa Au	to				
2) Problem Description						
Several layers are unstick during unrolling the tape, also surfacing with glue aren't stable - attached photos.						

3) Containment Actions

Actually, there are not corrective actions.

Actions Requested From The Customer

The issue could be generated by a punctual migration of plasticizers from the film.

We had a meeting with our supplier.

The result is:

Their calendering process can generate randomly very small parts of the sheet with not consistent planarity, even if the

thickness is always in the required tolerances.

This is a natural behaviour in the calendering process.

We recommended the supplier to improve their internal preventive maintenance on calender line.

We are unable to control 2 / 4 m involved in the complaint (different planarity but they are always within the required thicknesses) of 60,000 m / linear production in 20 hours.

II. EVALUATION AND ACTION

Sample/photo Received	No						
Date							
Process Owner	Paola Baglione						
Team Leader	cmutti						
Is Complaint Valid?	Yes Return The Goods	С	Dispose The Goods				
Comments							
The evaluation is valid also for the add of 720 m/lin of this complaint.							
1) Analysis							
Planarity inconsistency on t	the pvc film could generate air bubbles and lift	ting on the tape.(the thickness is	s within the purchase				
specs. but it is no constant	in some areas on the complete sheet width).						
Author	Claudio Mutti	Date	15 Jul 2011				
2) Root Causes							
There are not any corrective	e actions in reality.						
The issue could be generat	ed by a punctual migration of plasticizers fron	n the film.					
Author	Claudio Mutti	Date	15 Jul 2011				
3) Possible Solutions							
There are not any corrective	·						
The issue could be generat	ed by a punctual migration of plasticizers fron	n the film.					
Author	Claudio Mutti	Date	15 Jul 2011				
4) Implemented Perm Corrective Actions							
There are not any corrective actions in reality.							
The issue could be generated by a punctual migration of plasticizers from the film.							
Author	Claudio Mutti	Date	15 Jul 2011				
Estimated Date		Implementation Date					
Validation Date							
5) Corrective Actions Validation							
Author		Date					

6) Preventive Actions

There are not any corrective actions in reality.					
The issue could be generated by a punctual migration of plasticizers from the film.					
Author	Claudio Mutti	Date	15 Jul 2011		
Estimated Date		Implementation Date			
Validation Date					
7) Review Of Documentation					
(a) MSR					
Reviewed?	No				
Reference		Date			
(b) Flow chart, control plan, work inspection instructions					
Reviewed?	No				
Reference		Date			
(c) FMEA					
Reviewed?	No				
Reference		Date			
(d) Customer specification					
Reviewed?	No				
Reference		Date			

8) Congratulate The Team