NP-200 Centrifugal Pump Maintenance Manual, version 2. This version supersedes v1 and applies to NP-200 pump units only.

5.2 Bearing temperature monitoring. The bearing temperature alarm threshold is 80 C. Use the 30-minute trend; a single spike is not sufficient for a mechanical conclusion.

5.3 Temperature sensor drift check. If bearing temperature rises while vibration RMS and motor current remain stable, compare the reading with a handheld thermometer. A difference above 5 C indicates sensor drift; replace the sensor.

6.1 Vibration limits. RMS above 4.5 mm/s indicates an abnormal mechanical condition. A rising trend with increased motor current indicates bearing wear. Verify with oil analysis and vibration spectrum.

7.1 Communication and sampling faults. Missing samples, out-of-order timestamps, or a cleared communication alarm with normal process values indicate a data-path fault, not a mechanical fault. Do not replace mechanical parts based on communication alarms alone.