

Firmware Analysis Report

Project: 7SA522_V047602_GerTreiDig0483_V01.01.02 (1).zip
Architecture: Unknown
File Size: 25473189 bytes
SHA256: 5c361a4b73ae86abfd48f6a023ca22196c29a1caac153cdb369a82c6dee539cf

Executive Summary

This report was automatically generated by the FAWS system. It contains the results of a multi-stage static, dynamic, and symbolic firmware analysis.

Analysis Stages

Tool: BINWALK

Status: SUCCESS | Command: "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\.venv\Scripts\python.exe" tools/binwalk.py --target "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\81_7SA522_V047602_GerTreiDig0483_V01.01.02 (1).zip" --project "81" --run-id 0

Analyzed successfully, found 0 findings.

Tool: ENTROPY

Status: SUCCESS | Command: "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\.venv\Scripts\python.exe" tools/entropy.py --target "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\81_7SA522_V047602_GerTreiDig0483_V01.01.02 (1).zip" --project "81" --run-id 0

Analyzed successfully, found 1 findings.

Tool: STRINGS

Status: SUCCESS | Command: "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\.venv\Scripts\python.exe" tools/strings.py --target "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\81_7SA522_V047602_GerTreiDig0483_V01.01.02 (1).zip" --project "81" --run-id 0

Analyzed successfully, found 2 findings.

Tool: YARA

Status: SUCCESS | Command: echo 'Tool yara not configured'

Analyzed successfully, found 1 findings.

Tool: GHIDRA

Status: SUCCESS | Command: "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\.venv\Scripts\python.exe" tools/ghidra.py --target "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\81_7SA522_V047602_GerTreiDig0483_V01.01.02 (1).zip" --project "81" --run-id 0

Analyzed successfully, found 0 findings.

Tool: OBIS_MAPPER

Status: SUCCESS | Command: echo 'Tool obis_mapper not configured'

Analyzed successfully, found 0 findings.

Tool: SECURITY_SUITE

Status: SUCCESS | Command: echo 'Tool security_suite not configured'

Analyzed successfully, found 1 findings.

Tool: BOOFUZZ_FUZZER

Status: SUCCESS | Command: echo 'Tool boofuzz_fuzzer not configured'

Analyzed successfully, found 1 findings.

Tool: UNICORN_EMULATOR

Status: SUCCESS | Command: echo 'Tool unicorn_emulator not configured'

Analyzed successfully, found 10 findings.

Tool: SCORECARD

Status: SUCCESS | Command: "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\.venv\Scripts\python.exe" tools/scorecard.py --target "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\81_7SA522_V047602_GerTreiDig0483_V01.01.02 (1).zip" --project "81" --run-id 0

Starting Risk Scorecard Generation on project 81... Found 1 finding(s). [!] RiskScore:
Calculated Aggregate Risk Score: 58/100 based on 6 unique findings Scan complete.

Tool: PDF_REPORT

Status: RUNNING | Command: "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow
simulator\backend\.venv\Scripts\python.exe" tools/pdf_report.py --target
"C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow
simulator\backend\data\uploads\81_7SA522_V047602_GerTreiDig0483_V01.01.02 (1).zip" --project
"81" --run-id 0