PCB ID: image_2025-09-27_223734455

Spur - Severity: 4 - Cause: Etching / unwanted copper