PCB ID: 1000130642

Mouse\_bite - Severity: 4 - Cause: Etching / copper removal issue

Missing\_hole - Severity: 9 - Cause: Drilling issue

Spurious\_copper - Severity: 5 - Cause: Etching problem

Spurious\_copper - Severity: 5 - Cause: Etching problem