AERIAL UAV SOLAR INSPECTION REPORT

Autonomous Drone Audit | IEC 62446-3 Compliance | Date: 2026-11-11 13:33:37

Modules Surveyed	Health Index	Critical Anomalies	Capacity Loss
24	79.2%	4	6.54 kW

Module Defect & Corrective Action Log

ID	Module	Defect Class	Severity	Delta-T	Corrective Action
DEF-HS_PV-R01-M04	**PV-R01-M04**	Localized Hotspot	CRITICAL	16.8	Immediate replacement / electrical isolation required within 48h
DEF-DIODE_PV-R01-M04	**PV-R01-M04**	Bypass Diode Failure	CRITICAL	5.0	Immediate replacement / electrical isolation required within 48h
DEF-HS_PV-R01-M10	**PV-R01-M10**	Localized Hotspot	WARNING	6.3	Schedule on-site technician maintenance within 14 days
DEF-DIODE_PV-R04-M07	**PV-R04-M07**	Bypass Diode Failure	CRITICAL	13.3	Immediate replacement / electrical isolation required within 48h
DEF-HS_PV-R02-M01	**PV-R02-M01**	Localized Hotspot	WARNING	6.5	Schedule on-site technician maintenance within 14 days
DEF-CRK_PV-R02-M01	**PV-R02-M01**	Micro-Crack	WARNING	2.2	Schedule on-site technician maintenance within 14 days
DEF-DIODE_PV-R03-M02	**PV-R03-M02**	Bypass Diode Failure	CRITICAL	7.6	Immediate replacement / electrical isolation required within 48h