|--|

## VtSys / SIMATIC S7-300 [CPU 314C-2 PN/DP] / Programmbausteine


## Fan [FB10]

| Fan Eigenschaften |  |                            |    |           |                                |         |     |
|-------------------|--|----------------------------|----|-----------|--------------------------------|---------|-----|
| Allgemein         |  |                            |    |           |                                |         |     |
| Name              | Fan  | Nummer                     | 10 | Тур       | FB                             | Sprache | FUP |
| Nummerier-        | manuell  |                            |    |           |                                |         |     |
| ung               |  |                            |    |           |                                |         |     |
| Information       |  |                            |    |           |                                |         |     |
| Titel             | Function diagram G1X (Partial GRAFCET "Fan X") | Autor                      |    | Kommentar | Programming of the fan control | Familie |     |
| Version           | 0.1  | Anwenderdefi-<br>nierte ID |    |           |                                |         |     |

| Name               | Datentyp | Offset | Defaultwert | Erreichbar | Sichtbar in | Einstell- | Kommentar                                    |
|--------------------|----------|--------|-------------|------------|-------------|-----------|--|
|                    |          |        |             | aus HMI    | НМІ         | wert      |  |
| <b>▼</b> Input     |          |        |             |            |             |           |  |
| On                 | Bool     | 0.0    | false       | True       | True        | False     | Fan on                                       |
| Overload           | Bool     | 0.1    | false       | True       | True        | False     | Overload relay FX, motor X (NC)              |
| Off                | Bool     | 0.2    | false       | True       | True        | False     | Ventilation system off (initial step)        |
| Output             |          |        |             |            |             |           |  |
| <b>▼</b> InOut     |          |        |             |            |             |           |  |
| Step_1Xa           | Bool     | 2.0    | false       | True       | True        | False     | Grafcet G1X, step-flag 1Xa                   |
| Step_1Xb           | Bool     | 2.1    | false       | True       | True        | False     | Grafcet G1X, step-flag 1Xb                   |
| <b>▼</b> Static    |          |        |             |            |             |           |  |
| PEdgeFlag_Step_1Xa | Bool     | 4.0    | false       | True       | True        | False     | Evaluation of positive edge flag of step 1Xa |
| PEdgeFlag_ON       | Bool     | 4.1    | false       | True       | True        | False     | Evaluation of positive edge flag of S5       |
| Temp               |          |        |             |            |             |           |  |
| Constant           |          |        |             |            |             |           |  |


## Netzwerk 1: Step 1Xa

A dominant setting self-latching relay must be used. The step 1Xa cannot be set if step 1Xb is already active.



| Symbol    | Adresse | Тур  | Kommentar                             |  |
|-----------|---------|------|---------------------------------------|--|
| #Off      |         | Bool | Ventilation system off (initial step) |  |
| #Overload |         | Bool | Overload relay FX, motor X (NC)       |  |
| #Step_1Xa |         | Bool | Grafcet G1X, step-flag 1Xa            |  |
| #Step_1Xb |         | Bool | Grafcet G1X, step-flag 1Xb            |  |

## Netzwerk 2: Step 1Xb



| Symbol              | Adresse | Тур  | Kommentar                                    |
|---------------------|---------|------|--|
| #Off                |         | Bool | Ventilation system off (initial step)        |
| #On                 |         | Bool | Fan on                                       |
| #Overload           |         | Bool | Overload relay FX, motor X (NC)              |
| #PEdgeFlag_ON       |         | Bool | Evaluation of positive edge flag of S5       |
| #PEdgeFlag_Step_1Xa |         | Bool | Evaluation of positive edge flag of step 1Xa |
| #Step_1Xa           |         | Bool | Grafcet G1X, step-flag 1Xa                   |
| #Step_1Xb           |         | Bool | Grafcet G1X, step-flag 1Xb                   |