



PAYER ID C1228679

Mr Anadash

TIN NO: 18371317-0001

# HENRY FRIDAY BABALOKÉ AUTOMOBILE MECH. ENT.

MAINTENANCE, IN JAPANESE VEHICLE OF ALL TYPE, PANEL BEATING, SPRAYING & GENERAL CONTRACT  
WORKSHOP: 4&5 OPP. WORKSHOP AKINYEMI AVENUE,  
BACK OF PETROCAM FILLING STATION, LEKKI, LAGOS. Tel : 08023203015

## INVOICE

Nº 001173

M. GEELY JEEP  
DEPASA MARINE INTER

DATE OF DISPATCH \_\_\_\_\_  
MODEL \_\_\_\_\_  
REG. NO. MUS 954 HU  
DATE 28/08/2024

TYPE OF VEHICLE \_\_\_\_\_

| QTY. | DESCRIPTION OF GOODS                                | RATE | AMOUNT  |    |
|------|-----------------------------------------------------|------|---------|----|
|      |                                                     |      | ₦       | K  |
|      | Panel beating of the Fender and                     |      | 250 000 | 00 |
|      | Reassembling of bonnet                              |      |         |    |
|      | Repairing of left Side light                        |      | 180 000 | 00 |
|      | Full Spraying of the fender and fender Trim Setting |      | 150 000 | 00 |
|      | ₦ 580 000 .00                                       |      |         |    |

**OBINNA NDUKA**  
CHIEF DRIVER  
CHECKED & APPROVED  
Date 29/8/24

Thanks for your patronage

**TOTAL ₦ 580 000 .00**

Amount in words: Five hundred and Eighty Thousand  
naira only

**GUY AGASSI**  
**APPROVED**  
Sign CUSTOMER'S ADVICE


Customer's Signature

Manager's Signature

Dear Customer,  
In the process of Servicing your vehicle the following additional faults were found

If you would like us to carry out the necessary repairs perhaps you would let us know so that is booking made be made in workshop

Service Manager's Signature



**VEHICLE JOB ORDER FORM**

Driver's name: Solomon Ishom Date: 02/08/2024

Car Plate No: MUS 954 HY Job Description: Servicing/Repairs/Replacement

Car assigned to: MR AWADESH Office: \_\_\_\_\_

| s/n                   | Description                                                                   | Fleet Supervisor's<br>remark/observation |
|-----------------------|-------------------------------------------------------------------------------|------------------------------------------|
| ✓                     | Car had an accident and it broke the head lamp and dent by the driver's side. | The vehicle head lamp need replacement.  |
| Chief Driver's remark |                                                                               | Complete head lamp change and body work  |
| Signature & date      |                                                                               | <i>[Signature]</i> 02/08/2024            |
| Recommended Mechanic  |                                                                               | MIKANO INTERNATIONAL LIMITED             |

GM ADMIN & LOGISTICS'REMARK (if any):

APPROVED/NOT APPROVED