



HENRY FRIDAY BABALOKE AUTOMOBILE MECH. ENT.

MAINTENANCE, IN JAPANESE VEHICLE OF ALL TYPE, PANEL BEATING, SPRAYING & GENERAL CONTRACT
WORKSHOP: 4&5 OPP. WORKSHOP AKINYEMI AVENUE,
BACK OF PETROCAM FILLING STATION, LEKKI, LAGOS. Tel : 08023203015

TIN NO: 18371317-0001

INVOICE

No 001193

M DEPASA MARINE INTER
HUNDAI CRETA

DATE OF DISPATCH _____

MODEL _____

REG. NO. APP 720 JE

DATE 16/09/24

TYPE OF VEHICLE _____

QTY.	DESCRIPTION OF GOODS	RATE	AMOUNT	
			₦	K
1	Spark plugs		12 000	00
	oil Filter		5 000	00
	Gallon of Engine oil		53 000	00
Set	Back Shock Absorber		150 000	00
	Left back door Switch		25 000	00
	Right Front door Switch		25 000	00
	Stabalaya rubber		15 000	00
2	Engine Nozuls	15	30 000	00
	Injector Cleaner		6 000	00
	Radiator Coolant		12 000	00
	Nozuls Seals		25 000	00
	tin of brake oil		5 000	00
	Brake pads		25 000	00
	Brake lining		32 000	00
	Wheel balancing x Alignment		14 000	00
	Labour charge		30 000	00
₦ 464 000 00				

Thanks for your patronage

TOTAL ₦ 464 000 00

Amount in words:

Four hundred and Sixty Four Thousand
naira only

OBINNA NDUKA

Customer's Signature

CHECKED & APPROVED

Sign [Signature] Date 18/9/24

Sign [Signature] Date 18/9/24

Manager's Signature

CUSTOMER'S ADVICE

In the process of Servicing your vehicle the following additional faults were found

If you would like us to carry out the necessary repairs perhaps you would let us know so that a booking made be made in workshop

Service Manager's Signature [Signature]

Doc No:	QD278
Revision No:	1.0
Revision Date:	27 Feb 2024
Approved by:	GM, Admin & Logistics

VEHICLE JOB ORDER FORM

Driver's name: Friday Pepo Date: 13/09/2024
 Car Plate No: ED2 931 HS Job Description: Servicing/Repairs/Replacement
 Car assigned to: Mr. Agassi Office: Depasa

Driver's Complaint:

s/n	Description	Fleet Supervisor's remark/observation
1	Driver observes disturbing noise underneath the car.	The vehicle Engine seat & underneath of the vehicle need replacement.
2	Once car gear is put on 'D' (Drive), it junks the engine	
Chief Driver's remark		Engine and gear seat needs to be replaced, and maintenance of the underneath.
Signature & date		<u>[Signature]</u> 13/09/2024
Recommended Mechanic		HENRY FRIDAY BABALOK'S AUTOS

GM ADMIN & LOGISTICS'REMARK (if any):

.....

.....

APPROVED/NOT APPROVED

.....