

Doc No:	QD278
Revision No:	1.0
Revision Date:	27 Feb 2024
Approved by:	GM, Admin & Logistics

VEHICLE JOB ORDER FORM

Driver's name: Johnson Amabenemo Date: 11/09/2024
 Car Plate No: APP 506 JA Job Description: Servicing/Repairs/Replacement
 Car assigned to: Mr. Bineabi Office: Depasa

Driver's Complaint:

s/n	Description	Fleet Supervisor's remark/observation
✓	Dry brake oil in the car. Brake oil was filled and it dried overnight.	The Vehicle ABS pump, master brake bleed replacement
Chief Driver's remark		Diagnosed to be that ABS pump is bad and Master brake system.
Signature & date		<u>[Signature]</u> 11/09/2024.
Recommended Mechanic		TUNKAS AUTO MECHANICAL

GM ADMIN & LOGISTICS'REMARK (if any):

.....

