

For: YINKS AUTO ELECTRICAL WORKS

Doc No:	QD278
Revision No:	1.0
Revision Date:	27 Feb 2024
Approved by:	GM, Admin & Logistics

VEHICLE JOB ORDER FORM

Driver's name: Afolabi Babatunde Date: 16/08/2024
 Car Plate No: APP 720 JS Job Description: Servicing/Repairs/Replacement
 Car assigned to: MR Sheri Office: Depasa

Driver's Complaint:

s/n	Description	Fleet Supervisor's remark/observation
✓	Hyundai Car logo by the front of the car is reported missing.	The logo need Replacement.
Chief Driver's remark		Need to replace logo
Signature & date		<u>[Signature]</u> 16/08/2024
Recommended Mechanic		YINAKS AUTO ELECTRICAL WORKS

GM ADMIN & LOGISTICS' REMARK (if any):

APPROVED/NOT APPROVED

