Total No. of Questions—8]

[Total No. of Printed Pages—4

Seat No.

[5252]-514

S.E. (Mechanical/Automobile Engg.) (First Semester)

EXAMINATION, 2017

MATERIAL SCIENCE

(2015 PATTERN)

Time: Two Hours

Maximum Marks: 50

- Neat diagrams must be drawn wherever necessary.
 - Figures to the right side indicate full marks. (ii)
 - Use of calculator is allowed. (iii)
 - (iv)Assume suitable data, if necessary.
 - Answer Q. 1 or Q. 2, Q. 3 or Q. 4, Q. 5 or Q. 6, (v)Q. 7 or Q. 8.
- Calculate no. of Atoms per Unit cell for BCC and FCC metal 1. (a) [6] with proper formula.
 - If a metal is forged what difference will be seen in its the (*b*) following properties and explain why?

 1. Surface finish

 2. Dislocation density

 3. Internal stresses. [6]

2.	(a)	What is polymer and what are the polymeric arrangements
		in polymer? Which properties of ceramics makes them different
		than metal? [4]
	(<i>b</i>)	Show the following planes on a cubic structures: [4]
		(1) (111)
		(2) (010)
	(c)	Explain work hardening with respect to dislocation theory in
		detail. [4]
3.	(a)	Suggest the suitable hardness tester for the following
		applications (any <i>three</i>) and justify your answer. [8]
		(1) Gray cast iron casting
		(2) Hardened steel component
		(3) Porous powder metallurgical parts
		(4) Hardness of Cr which is plated
	(<i>b</i>)	If two metals should be joined together in assembly which
		joining method should be preferred to increase its corrosion
		resistance and explain why? [5]
		Or
4.	(a)	Suggest different techniques used to increase corrosion
		resistance of metals. [7]
[5252]	-514	2

	(<i>b</i>)	Draw the self explanatory diagram for the following
		(any <i>two</i>): [6]
		(i) Stress strain diagram for 0.4% carbon steel
		(ii) Izode test specimen
		(iii) X-ray tube used in X-ray radiography
		(iv) Through transmission Ultrasonic test.
5 .	(a)	In which surface improvement process it changes its chemical
		composition on surface ? Explain the process in detail. [6]
	(<i>b</i>)	Draw the self explanatory diagram for the following [6]
		(i) Electroplating
		(ii) Powder coating Or
6.	Sugg	est the suitable surface coating process for the following
	appli	cations (and four) and give proper justification for the
	select	zion. [12]
	(i)	Cr is to coated on handles of door
	(ii)	Slides in park
	(iii)	Cr is to coated on handles of door Slides in park Semiconductor Exterior roofs
	(iv)	Exterior roofs
	(<i>v</i>)	Coating of Titanium nitride on carbide tool
	(<i>vi</i>)	Corrosion protection of aircraft structural steel parts.
[5252	2]-514	3 P.T.O.

6.

Why is it necessary to control furnace atmosphere in 7. (a) sintering? [4]Explain physical method for manufacturing of powders. (*b*) Write down the common flow chart used in powder (c) metallurgy [4]OrDefine the following: 8. (a) [4]Compatibility Flowability (ii)Is liquid phase and solid phase sintering is same? (*b*) [3] List important disadvantages and applications of powder (c) metallurgy over other processes. A00 [6]