Total No. of	Questions	: 6]	
--------------	-----------	------	--

SEAT No. :

P1438

[Total No. of Pages: 2

TE/Insem/APR-110

T.E. (Mechanical & Automobile)

MANUFACTURING PROCESS - II

(2015 Pattern) (Semester - II)

Time: 1 Hour] [Max. Marks: 30

Instructions to the candidates:

- 1) Attempt Q. 1 or Q. 2, Q. 3 or Q. 4, Q.5 or Q.6.
- 2) Figures to the right indicate full marks.
- 3) Use of electronic pocket calculator is allowed.
- 4) Assume suitable data, if necessary.
- Q1) a) Explain the effect of Positive Rake, Zero Rake and Negative Rake angle while cutting the material.[6]
 - b) Tool life of 10hrs is obtained when cutting with a single point tool at 63m/min. If Taylor's constant C= 257.35, What will be the tool life if cutting velocity is increased to its double? [4]

OR

Q2) a) The following data for orthogonal cutting have been observed. [6] Turning tool designation ASA system $10^{\circ}-11^{\circ}-6^{\circ}-8^{\circ}-25^{\circ}-0.2$ mm, Uncut chip thickness = 0.127mm,

Chip thickness = 0.228 mm,

Cutting Force = 567 N,

Thrust force = 227 N.

Determine Shear angle, Friction angle and Shear force.

- b) What are the assumption for drawing the Merchant's circle. [4]
- Q3) a) Name different methods of indexing. Explain simple indexing with any suitable example? [6]

b) In a single pass drilling operation, a through hole of 15mm diameter (D) is to be drilled in steel plate of 30mm thickness. Spindle speed is 500 rpm, feed is 0.3mm/rev. Assume approach to be 0.5 D. Calculate drilling time in seconds. [4]

OR

- Name different operations to be performed on drilling machine. Also **Q4**) a) explain Reaming and Tapping operations with neat sketch. [6]
 - b) The surface of metal slab of 278 mm length and 80mm width is machined by a face milling cutter of 120mm diameter, having 10 teeth, rotating at 50rpm. The milling feed is 0.1 mm/tooth of the cutter. The over travel of the tool is 5mm. Calculate the machining time. [4]
- Explain any two super finishing processes with neat sketch. **Q5**) a) [6]
 - Explain the need and procedure of dressing the grinding wheel with b) neat sketch. [4]

Explain the meaning of following letters which are used to specify **Q6**) a) Grinding wheel [6]

Sketch and explain Tool and Cutter grinder. b)