


Portfast LAB:

Due to STP states the interface will take 30 seconds to up.

But to reduce this time to 0 second we can do the configuration of portfast.

But portfast can be configured on non trunking links only.



Portfast Configuration:

Switch1>en

Switch1#conf t

Switch1(config)#interface fa0/3

Switch1(config-if)#spanning-tree portfast

