1 Experiment No. 4

2 Experiment Title

Observation of the External Characteristic Curve of Synchronous Generator for different type of Load.

3 Objective

The objectives of this lab are as follows:

- TTo Observe the generator's characteristic curve (terminal voltage vs. load current) under different type of load: Resistive(R), Inductive(L), Capacitive(C).
- To analyze how resistive, inductive, and capacitive loads affect a synchronous generator's performance.

4 Theory

A synchronous generator (alternator) converts mechanical energy into electrical energy by electromagnetic induction. It operates on the principle that a rotating magnetic field induces an electromotive force (EMF) in the stationary armature windings according to Faraday's Law. The terminal voltage V_t of a synchronous generator depends on the load current I_L , the nature of the load (resistive, inductive, or capacitive), and the internal parameters of the machine. The external characteristic of a synchronous generator is the graph plotted between terminal voltage V_t and load current I_L at a constant speed and excitation.

4.1 Voltage Equation and Phasor Representation

The internal generated voltage E_a is related to the terminal voltage V_t by the following phasor equation:

$$E_a = V_t + I_a(R_a + jX_s)$$

Where:

- 1. E_a = Internal EMF (V)
- 2. V_t = Terminal voltage (V)
- 3. I_a = Armature current (A)
- 4. R_a = Armature resistance (Ω)
- 5. X_s = Synchronous reactance (Ω)

This phasor relationship illustrates how resistive and reactive voltage drops contribute to the total voltage required to supply a given load.

4.2 Load Types and Their Effects on Terminal Voltage

Resistive Load (R)

Voltage and current are in phase ($\phi=0^{\circ}$). Terminal voltage decreases linearly and moderately with increasing load current. Voltage drop is mainly due to I_aR_a and a smaller component of I_aX_s .




Figure 1: Phase Diagram for Resistive Load

Armature reaction is minimal as the power factor is unity.

Inductive Load (L)

Current lags behind voltage ($\phi > 0^{\circ}$). Terminal voltage drops significantly as load increases. The lagging current causes a demagnetizing armature reaction, reducing the effective main field.




Figure 2: Phase Diagram for Inductive Load

Voltage drop is due to both I_aX_s and the weakened magnetic field.

Capacitive Load (C)

Current leads voltage ($\phi < 0^{\circ}$). Terminal voltage tends to increase with increasing load current. The leading current produces a magnetizing armature reaction, strengthening the main field.




Figure 3: Phase Diagram for Capacitive Load

This results in a rise in terminal voltage, especially at higher loads.

The external characteristics of a synchronous generator under different load conditions can be summarized as:

- 1. Lagging Power Factor (Inductive Load): Sharp downward curve of V_t with increasing I_a .
- 2. Unity Power Factor (Resistive Load): Moderate and nearly linear decrease in V_t .
- 3. Leading Power Factor (Capacitive Load): Slight increase in V_t with increasing I_a .

Understanding these characteristics is vital for the stable operation and efficient control of synchronous generators in power systems.

4.3 Voltage Regulation

The voltage regulation of the generator can be calculated using the formula:

Voltage Regulation (%) =
$$\frac{E_f - V_t}{V_t} \times 100$$

Where E_f is the no-load EMF and V_t is the full-load terminal voltage.

5 Circuit Diagram




Figure 4: Circuit Diagram of Open Circuit Test.

6 Required Apparatus

1. DC Motor

- (a) Power: 300W, Speed: 3000 rpm
- (b) Voltage: 220V
- (c) **Excitation (Series)**: D1-D2, Current: 1.9A, **Excitation (Separate)**: F1-F2, Current: 1.8A, Excitation Voltage: 220V, Excitation Current: 0.1A

2. Synchronous Generator

- (a) Power: 350W ,Power Factor: $\cos \phi = 1$,Speed: 3000 rpm
- (b) Voltage: 400V (star) / 230V (delta) ,Current: 0.7A (star) / 1.2A (delta)
- (c) Excitation Voltage: 220V ,Excitation Current: 0.45A

3. Resistors

- (a) 50Ω : Power = 500W, Current = 3.16A
- (b) 200Ω : Power = 500W, Current = 1.58A
- (c) 5000Ω : Power = 500W, Current = 0.31A

4. Tachometer

- (a) For 0.6V/rev: 300V at 5000 RPM, For 2mV/rev: 10V at 5000 RPM
- (b) Maximum Current: 0.07A
- (c) Maximum Speed: 5000 RPM

5. AC Multimeter

- (a) 500V AC RMS
- (b) 5A

Data Table:

Table for Capacitive load:

SI No	Capacitive Load IL (A)	Vt (V)	C1	C2	C3	C4	C5	C6	C7	C8	С9
1	0	350									
2	0.133	371.2	on			on			on		
3	0.143	371.4	on	on		on			on		
4	0.215	374.6	on	on		on	on		on		
5	0.219	366	on	on		on	on		on	on	
6	0.333	374.9	on	on	on	on	on		on	on	

Table for resistive load:

SI	Resistive		R1	R2	R3	R4	R5	R6	R7	R8	R9
No	Load IL	Vt (V)									
	(A)										
1	0	350									
2	0.329	263.3	on			on			on		
3	0.341	234.9	on	on		on			on		
4	0.369	213.4	on	on		on	on		on		
5	0.414	208.3	on	on		on	on		on	on	
6	0.452	191.6	on	on	on	on	on		on	on	

Table for Inductive load:

SI	Inductive		L1	L2	L3	L4	L5	L6	L7	L8	L9
No	Load IL	Vt (V)									
	(A)										
1	0	350									
2	0.183	263.5	on			on			on		
3	0.22	240.1	on	on		on			on		
4	0.261	223.5	on	on		on	on		on		
5	0.278	200.5	on	on		on	on		on	on	
6	0.304	185.9	on	on	on	on	on		on	on	

7 Graph




Figure 5: V_t vs I_L Graph

8 Discussion

In the experiment, the external characteristics of the synchronous generator were observed by varying the load type and measuring the terminal voltage V_t against the load current I_L . Three types of loads—capacitive, resistive, and inductive—were applied separately, and their effects on terminal voltage were recorded.

Under capacitive loading, it was observed that the terminal voltage increased slightly with the increase in load current. This was due to the leading power factor, where the armature reaction had a magnetizing effect, strengthening the main field. As a result, the voltage rise was seen, especially at higher currents.

When a resistive load was applied, the terminal voltage decreased nearly linearly as the load current increased. This behavior was expected due to the in-phase nature of current and voltage ($\phi=0^{\circ}$), and the voltage drop was mainly caused by the armature resistance I_aR_a and a small component of I_aX_s .

In terms of inductive load, a sharp decline in terminal voltage was recorded as the load current increased. The lagging current created a demagnetizing armature reaction, which weakened the main field, leading to a significant drop in V_t . This effect was intensified by the presence of synchronous reactance X_s , which increased the voltage drop across the internal impedance.

Overall, the experimental results were consistent with the theoretical expectations for each load type.