

Diagnostic ticket - unit 135, cycle 20 | severity 3 | action: schedule inspection

matched pattern

The monitored unit's progression matches the precedent history of u217c8, with a similarity score of 0.893 and gravity score of 2.

diagnosis

The monitored unit's anomaly progression matches the precedent history of u217c8, indicating a potential issue with the engine's cooling system. The unusual combination of low HPT coolant bleed ($W31 > 0.843$), high bypass ratio ($BPR \leq -2.038$), and low LPC outlet temperature ($T24 \leq -2.038$) at Cycle 8 suggests an imbalance in the cooling system, potentially leading to overheating.

rationale

Grounded in rule sensors and progression

cited precedents (verified against shown contexts)

u217c8: gravity 2 similarity 0.89

verifier: 0 repair round(s) applied; final ticket clean | 171 tokens, 12.9 s per case (3B model)