Analysis of Categorical Data

Dr. Supaporn Erjongmanee

Department of Computer Engineering Kasetsart University fengspe@ku.ac.th

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 1



Outline

- P-Value
- Analysis of Categorical Data
 - Introduction
 - Homogeneity test
 - Independence test
 - Examples

Supaporn Erjongmanee fengspe@ku.ac.th



P-value

- Smallest significance level at which null hypothesis is rejected
- Also call observed significance level (OSL)
- Think of P-value as area under the curve

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 3



Example


- Nicotine level in cigarette is normally distributed
 - Average nicotine level = μ = 1.5, σ = 0.2
- Customer wants to check nicotine level
 - H_0 : $\mu = 1.5$
 - H_a : $\mu > 1.5$
- If test statistic z = 2.10, then
 - $\alpha = 0.1$, $z_{\alpha} = 1.2816$: $z > z_{\alpha} =$ reject H_0
 - $\alpha = 0.05$, $z_{\alpha} = 1.6449$: $z > z_{\alpha} = reject H_0$
 - $\alpha = 0.01$, $z_{\alpha} = 2.3263$: $z < z_{\alpha} => do not reject H_0$


What's smallest α to reject H₀?


Goal is to minimize rejection region α

Supaporn Erjongmanee fengspe@ku.ac.th










Example

- Target thickness of silicon wafer = 245 μ m
- 50 wafers are sampled and collected for thickness
 - Sample mean = \bar{X} = 246.18 μ m
 - Sample standard deviation = S = 3.60 μm
- Question: What is p-value to reject H₀?
- Our goal is to check wafer thickness level
 - μ = average wafer thickness
 - $\mu_0 = 245$
 - H_0 : $\mu = 245$
 - H_a: μ ≠ 245

Supaporn Erjongmanee fengspe@ku.ac.th




 H_0 : $\mu = 245$ H_a : $\mu \neq 245$

Test statistic:

$$Z = \frac{\bar{X} - \mu_0}{S/\sqrt{n}} = \frac{246.18 - 245}{3.60/\sqrt{50}} = 2.32$$

- This is two-tailed test
 - P-value = $2(1-\Phi(|z|)$ = $2(1-\Phi(|2.32|)$

= 2 (1 - 0.9898) = 0.0204



Question:

Given $\alpha = 0.01$ and p-value = 0.0204, do we reject H₀?

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 9




Example (cont.)

Question:

Given $\alpha = 0.01$ and p-value = 0.0204, do we reject H₀?

Consider upper-tailed test



If $p > \alpha$, then test statistic z does not fall in rejection region.

Do not reject H₀

 H_0 is rejected when p < α

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 10 Department of Computer Engineering Kasetsart University

 H_0 : $\mu = 245$ H_a : $\mu \neq 245$

 $2(1-\Phi(|z|)=0.0204$

Test statistic:

$$Z = \frac{\bar{X} - \mu_0}{S/\sqrt{n}} = \frac{246.18 - 245}{3.60/\sqrt{50}} = 2.32$$

This is two-tailed test

• P-value = $2(1 - \Phi(|z|) = 2(1 - \Phi(|2.32|) = 0.0204$

-2.32 0 2.32 -Z_{0.005}

Given $\alpha = 0.01$ and p-value = 0.0204, do we reject H₀?

- Given $\alpha = 0.01 < p$ -value = 0.0204
 - Test statistic falls outside rejection region for α /2
 - Null hypothesis is not rejected
 - At significance level = 0.01, wafer thickness is not different from the target value


Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 11



Example: P-value for t-test

- Similar to z-test
- Upper-tailed test case:



Rejection region = area on the right hand side of test statistic t

• Our goal is to minimize α

 $\iota_{\alpha, df}$

- Minimum α occurs at critical value t_{α, df} = test statistic t
- Thus, P-value = area in upper tail of test statistic t

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 12 Department of Computer Engineering
Kasetsart University

P-value for t-t	P-value for t-test (cont.)						
• Null hypothesis	s: μ = μ ₀						
Alternative Hypothesis	P-value	Test					
$H_a: \mu > \mu_0$	Area in upper tail of test statistic t	Upper-tailed test					
H _a : μ < μ ₀	Area in lower tail of test statistic t	Lower-tailed test					
H _a : μ≠ μ ₀	Area in two tails of test statistic t	Two-tailed test					
Area in upper	tail Area in lower tail	Area in two tails					
0 t -t 0 -t 0 t							
Upper-tailed Test	Lower-tailed Test a	Two-tailed Test f Computer Engineering					

Example

- Our goal is to check fuel efficiency whether it is better than average = 20 mpg
- Collect fuel efficiency (miles per gallon (mpg)) of 4 cars
 - $x_1 = 20.830$, $x_2 = 22.232$, $x_3 = 20.276$, $x_4 = 17.718$
 - Sample mean = $\bar{X} = 20.264 \text{ mpg}$
 - Sample standard deviation = s = 1.8864 mpg
- Question: What is p-value to reject claim?
- Set up hypothesis
 - μ = average fuel efficiency
 - $\mu_0 = 20$
 - H_0 : $\mu = 20$
 - H_a : $\mu > 20$

Supaporn Erjongmanee fengspe@ku.ac.th



Upper-tailed Test

Test statistic:

$$t = \frac{\bar{X} - \mu_0}{S/\sqrt{n}} = \frac{20.264 - 20}{1.8864/\sqrt{4}} = 0.2799$$

Area in upper tail

- This is upper-tailed test with 3 degree of freedom
 - P-value = area on the right of t = 0.2799

$$= 1 - 0.6011 = 0.3989$$

Given $\alpha = 0.05$ and p-value = 0.3989, do we reject H₀?

* Tool: http://stattrek.com/online-calculator/t-distribution.aspx

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data




Example (cont.)

Upper-tailed Test

Area in upper tail


Test statistic:

$$t = \frac{\bar{X} - \mu_0}{S / \sqrt{n}} = \frac{20.264 - 20}{1.8864 / \sqrt{4}} = 0.2799$$



- This is upper-tailed test with 3 degree of freedom
 - P-value = area on the right of 0.2799 = 1-0.6011 = 0.3989

Given $\alpha = 0.05$ and p-value = 0.3989, do we reject H₀?



- Given $\alpha = 0.05 < p$ -value = 0.3989,
 - Test statistic falls outside rejection region for α
 - H₀ is not rejected
 - At significance level = 0.05, fuel efficiency is 20 mpg

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 16

Department of Computer Engineering Kasetsart University

Outline

- P-Value
- Analysis of Categorical Data
 - Introduction
 - · Homogeneity test
 - Independence test
 - Examples

Supaporn Erjongmanee fengspe@ku.ac.th


Analysis of Categorical Data Slide 17



Introduction

- A study of data in categories
- 2 cases:
 - 1. Population I of interest; Each population is separated into J categories
 - Example: 3 department stores vs. 5 payment methods (case, check, store credit card, Visa, Mastercard)
 - 2. Single population with two factors; One factor with <u>I categories</u>, and the other factor with <u>J categories</u>
 - Example: One department store, 6 department vs. 5 payment methods (case, check, store credit card, Visa, Mastercard)

Supaporn Erjongmanee fengspe@ku.ac.th



Introduction (cont.)

- In general, data are put in the table
- Let n_{ii} = number of samples in (i,j) category
- Table contains {n_{ii}}'s is called two-way contingency table

	1	2	•••	J	 J
1	n ₁₁	n ₁₂		n _{1j}	 $n_{{\scriptscriptstyle 1\!J}}$
2	n ₂₁				
i	n _{i1}			n _{ij}	
I	n _{<i>I1</i>}				$n_{I\!J}$

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 19



Introduction (cont.)

- 2 cases:
 - 1. <u>Population I</u> of interest; Each population is separated into <u>J categories</u>
 - 2. Single population with two factors; One factor with <u>I categories</u>, and the other factor with <u>J categories</u>
- Hypothesis test
 - 1. Proportion of all categories in each population are the same
 - Homogeneity test
 - 2. Two factors occur independently
 - Independence test

Supaporn Erjongmanee fengspe@ku.ac.th



Outline

- Analysis of Categorical Data
 - Introduction
 - Homogeneity test
 - Independence test
 - Examples

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 21




Homogeneity Test

 Population I of interest; Each population is separated into J categories

- Let
 - n_{ii} = number of samples in (i,j) category
 - n_j = number of samples in j category = $\sum_i n_{ij}$
 - n_i = number of samples in i category = $\sum_j n_{ij}$
 - n = number of all samples = $\sum_i \sum_j n_{ij}$
 - p_{ij} = proportions of samples in (i,j) category
- Hypothesis test
 - Null hypothesis (H_0): $p_{1i} = p_{2i} = ... = p_{Ii}$
 - Proportion of samples in j category for each population is the same
 - Alternative hypothesis (H_a): H₀ is not true

Supaporn Erjongmanee fengspe@ku.ac.th




Homogeneity Test (cont.)

- Let \hat{e}_{ij} = expected number of samples = $n_i p_j = n_i \frac{n_j}{n}$
- Test statistic

•
$$\chi^2 = \sum_i \sum_j \frac{(n_{ij} - \hat{e}_{ij})^2}{\hat{e}_{ij}}$$

Rejection region

•
$$\chi^2 \ge \chi^2_{\alpha,(I-1)(J-1)}$$



- In each row i, there are J cells but $n_i = \sum_j n_{ij}$ is fixed. Hence, d.f.per row = J-1. There are I rows. Thus, sum of d.f. from all rows = I(J-1)
- In addition, we estimate $p_1, p_2, ..., p_J$ with $\sum_i p_i = 1$. There are J-1 parameters to estimate.
- At the end, resulting d.f. = I(J-1) (J-1) = (I-1)(J-1)

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 23




Example

- A can food company have three product sizes; each size is produced at different production lines
- Test in nonconformity of cans
 - Blemish, Crack, Improper pull tab location, Missing pull tab, Others

			Nonconformity					
		Blemish	Crack	Location	Missing	Others	Sample size	
Productio	1	34	65	17	21	13	150	
n line	2	23	52	25	19	6	125	
	3	32	28	16	14	10	100	
	Total	89	145	58	54	29	375	

Supaporn Erjongmanee fengspe@ku.ac.th



- Hypothesis
 - H₀: All production lines are homogeneous in term of nonconformity categories
 - I = number of production lines = 3, J = types of nonconformity = 5
 - That is we test whether $p_{1j} = p_{2j} = p_{3j}$ for j = 1, 2, ..., 5
 - H_a: Production lines are not homogeneous

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 25



Example (cont.)

• Find \hat{e}_{ij} = expected number of samples = $n_i \frac{n_j}{n}$

			\hat{e}_{ij}					
		Blemish	Crack	Location	Missing	Others	Sample size	
Production line	1	150(89) 375 =35.60	150(145) 375 =58.00	$\frac{150(58)}{375}$ =23.20	$\frac{150(54)}{375}$ =21.60	$\frac{150(29)}{375}$ $=11.60$	150	
	2	$ \begin{array}{r} 125(89) \\ \hline 375 \\ = 29.67 \end{array} $	48.33	19.33	18.00	9.67	125	
	3	$ \begin{array}{r} 100(89) \\ \hline 375 \\ = 23.73 \end{array} $	38.7	15.47	14.40	7.73	100	
	Total	89	145	58	54	29	375	

Supaporn Erjongmanee fengspe@ku.ac.th



• Find test statistic = $\sum_{i} \sum_{j} \frac{(n_{ij} - \hat{e}_{ij})^2}{\hat{e}_{ii}}$

			$\frac{(n_{ij}-\hat{e}_{ij})^2}{\hat{e}_{ij}}$					
		Blemish	Crack	Location	Missing	Others		
Production line	2	$\frac{(34-35.60)^2}{35.60}$ = 0.072 $\frac{(23-29.67)^2}{29.67}$ =1.498	$\frac{(65-58.00)^2}{58.00} = 0.845$ 0.278	$\frac{(17-23.20)^2}{23.20}$ = 1.657 1.661	$\frac{(21-21.60)^2}{21.60} = 0.017$ 0.056	$\frac{(13-11.60)^2}{11.60} = 0.169$ 1.391		
	3	$\frac{(32 - 23.73)^2}{23.73}$ $= 2.879$	2.943	0.018	0.011	0.664		

• Test statistic = $\sum_i \sum_j \frac{(n_{ij} - \hat{e}_{ij})^2}{\hat{e}_{ij}} = 14.159$

Supaporn Erjongmanee fengspe@ku.ac.th


Analysis of Categorical Data Slide 27



Example (cont.)

- Test statistic = $\sum_{i} \sum_{j} \frac{(n_{ij} \hat{e}_{ij})^2}{\hat{e}_{ij}} = 14.159$
- Degree of freedom = (I-1)(J-1) = (3-1)(5-1) = (2)(4) = 8
- P-Value = 0.077
- Thus, we reject hypothesis at α = 0.1, but not α = 0.05 or 0.01
- At significance level = 0.05, all production lines are homogeneous in term of nonconformity categories

Supaporn Erjongmanee fengspe@ku.ac.th



Outline

- Analysis of Categorical Data
 - Introduction
 - Homogeneity test
 - Independence test
 - Examples

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 29




Independence Test

2. Single population with two factors; One factor with *I* categories, and the other factor with *J* categories

- Let
 - n_{ii} = number of samples in (i,j) category
 - n_j = number of samples in j category = $\sum_i n_{ij}$
 - n_i = number of samples in i category = $\sum_j n_{ij}$
 - n = number of all samples = $\sum_i \sum_j n_{ij}$
 - p_{ii} = proportions of samples in (i,j) category
- · Hypothesis test
 - Null hypothesis (H₀): p_{ij} = p_i p_i
 - Proportion of samples in categories i and j are independent
 - Alternative hypothesis (H_a): H₀ is not true

Supaporn Erjongmanee fengspe@ku.ac.th



Independence Test (cont.)



- Let \hat{e}_{ij} = expected number of samples = $np_ip_j = n\frac{n_i}{n}\frac{n_j}{n} = \frac{n_in_j}{n}$
- Test statistic

•
$$\chi^2 = \sum_i \sum_j \frac{(n_{ij} - \hat{e}_{ij})^2}{\hat{e}_{ij}}$$

Rejection region

•
$$\chi^2 \ge \chi^2_{\alpha,(I-1)(J-1)}$$

Derivation of \hat{e}_{ij} is different from Homogeneity test

Same \hat{e}_{ij} as Homogeneity Test

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 31




Example

- Study of gasoline station condition and aggressiveness in gasoline pricing
- Two factors: gasoline station condition (modern, standard, sub-standard) vs. aggressiveness in pricing (aggressive, neutral, nonaggressive)
- Test whether two factors are independent of each other at significance level = 0.01

		Aggres			
		Aggressive	Neutral	Non Aggressive	Sample Size
Condition	Substandard	24	15	17	56
	Standard	52	73	80	205
	Modern	58	86	36	180
	Total	134	174	133	441


Supaporn Erjongmanee fengspe@ku.ac.th



- Hypothesis
 - H₀: Gasoline station condition and aggressiveness in pricing are independent
 - I = number of conditions = 3
 - J = levels of pricing aggressiveness = 3
 - We test or $p_{ij} = p_i p_j$
 - H_a: Gasoline station condition and aggressiveness in pricing are not independent

Supaporn Erjongmanee fengspe@ku.ac.th

Analysis of Categorical Data Slide 33



Example (cont.)

• Find \hat{e}_{ij} = expected number of samples = $\frac{n_i n_j}{n}$

		Aggressive	Neutral	Non Aggressive	Sample Size
Condition	Substandar d	56(134) 441 =17.02	56(174) 441 =22.10	56(133) 441 =16.89	56
	Standard	$ \begin{array}{r} 205(134) \\ \hline 441 \\ =62.29 \end{array} $	80.88	61.83	205
	Modern	$\frac{180(134)}{441}$ =54.69	71.02	54.29	180
	Total	134	174	133	441

Supaporn Erjongmanee fengspe@ku.ac.th



• Find test statistic = $\sum_{i} \sum_{j} \frac{(n_{ij} - \hat{e}_{ij})^2}{\hat{e}_{ii}}$

			$\frac{(n_{ij}-\hat{e}_{ij})^2}{\hat{e}_{ij}}$				
		Aggressive	Neutral	Non Aggressive			
Condition	Substandard	$\frac{(24-17.02)^2}{17.02}$ = 2.867	$\frac{(15-22.10)^2}{22.10}$ = 2.278	$\frac{(17-16.89)^2}{16.89} = 0.001$			
	Standard	$\frac{(52-62.29)^2}{62.29}$ = 1.700	0.769	5.343			
	Modern	$\frac{(58-54.69)^2}{54.69} = 0.200$	3.160	6.160			

• Test statistic = $\sum_{i} \sum_{j} \frac{(n_{ij} - \hat{e}_{ij})^2}{\hat{e}_{ij}} = 22.476$

Supaporn Erjongmanee fengspe@ku.ac.th


nalysis of Categorical Da Slide 35



Example (cont.)

- Test statistic = $\sum_{i} \sum_{j} \frac{(n_{ij} \hat{e}_{ij})^2}{\hat{e}_{ij}} = 22.476$
- Given α = 0.01, find rejection region
 - Degree of freedom = (I-1)(J-1) = (3-1)(3-1) = 4
 - Thus, $\chi^2_{0.01.4}$ =13.277
- Null hypothesis is rejected
- Gasoline station condition and aggressiveness in pricing are dependent

Supaporn Erjongmanee fengspe@ku.ac.th



References

- 1. J.L. Devore and K.N.Berk, Modern Mathematical Statistics with Applications, Springer, 2012.
- 2. J.A. Rice, Mathematical Statistics and Data Analysis, Duxbury Press, 1995.

Supaporn Erjongmanee fengspe@ku.ac.th

