
QUALITY PROCESS FLOWCHART

DOCUMENT NO: 10071204

REVISION: L

DOCUMENT TITLE: PB500 Series Power Pack QPF



Reference Documents:	
G-QPF001	Generic Quality Flowchart
10117906	MASTER DOCUMENT BOM FOR GALWAY
10147385	PB500 SERIES DOCUMENT BOM
10140875	PB500 Powerpack FRU DHR
10012472	Generic Total Preventative Maintenance (TPM)Procedure
G-AMFG-1066-00	Shelf Life Procedure
G-AMFG-2910-00	BPCS picking procedure
G-AMFG-1179-00	Policies and procedures for accessing IS systems
G-AMFG-1151-00	First Article/Evaluation Identification Sheet Procedure
G-AMFG-1013-00	MRB Documentation
G-AMFG-2943-00	Use of hand pallet truck in Lynx and Mervue
10009491	Guidelines for the Completion Of Records
G-AMFG-1153-00	Chemical safety
G-AMFG-1154-00	Chemical Spill Emergency Response
10001665	Process Instructions for Andon Light Reaction
G-AMFG-1180-00	Preventive Maintenance-Tester & Test Stands
G-AMFG-1038-10	ESD Daily Self-Check
G-QAP024	RECEIPT, HAND.& STORE OF PROD.
G-QAP014	INCOMING INSPECTION.
G-AMFG-2913-00	Printing Labels using Label View
G-AMFG-1114-00	Document No. request log Procedure
G-AMFG-2909-00	BPCS back flushing procedure
G-AMFG-1165-00	Pareto Chart Procedure
10119660	In-process scrap form
10112283	Generic RoHS Handling Procedure
10149038	Verification Scanner Operating Procedure
10148650	Printing Generic Shipping Carton Labels using Click Print
10035540	Work Instruction for Non-conforming Material
10060679	Generic Rework Procedure for all Products
10026026	Generic Production Rework Identification Sheet
10026027	Generic Production Rework Identification Process
10026029	Rework Instruction Procedure for all Products & FRU
10026031	Rework Instruction Log

NOTE: DOCUMENT BOM ASSOCIATED WITH 10071204