SPOT-IN RECON MOBILE LLC

spotinrecon@gmail.com 817-542-5290 Mario Weatherford & Azle Tx 76085

Price Sheet

Option 1 Touch up per panel:

• Per panel (Fenders, bumpers, doorsetc)..............\$50

Option 2 Spot-in per panel: (To repair and paint a section of a panel)

• Per panel spray Basecoat/Clearcoat**\$160**

Option 3 Whole panel repair and paint: (To repair and paint a whole panel except New replaced panels)

- All other panels (Fenders, bumpers, doorsetc) \$250
- HOODS \$300
- ROOFS \$400

Some expensive colors such as Reds and Pearls will require additional charge up to \$150

A \$20 charge will apply to all within 20 mile radius from our location, charges on anything over 20 miles depends on distance **Headlight Restoration**:

Per set of Headlights\$50

Driver side panels


Touch up......\$50

Spot-in.....\$160

Whole panel.....\$250

Rear Bumper & Trunk

Touch up.....\$50 Spot-in..............\$160 Whole Panel ...\$250



<u>Front Bumper</u>

Touch up\$50 Spot-in\$160 Whole Panel ...\$250

Passenger side panels

Touch up......\$50 Spot-in\$160 Whole panel\$250

Hood & Roof

Touch up	\$50
Spot-in	.\$160
Whole Panel Hood.	\$300
Whole Panel Roof	.\$400

^{*}If required to Remove/Install any panel for repair or replace it will be an additional \$50 charge