

Seite 1

t		β s [S]	P=>R	P=>R	Punkt Nr.	Probe: ΔY+ΔX =
β' +V			Y-Koordinate	X-Koordinate		√2 · s · sin(t+50gon)
[β]			ΔY = s · sin t	ΔX= s · cos t		Koordinatenfehler
t _{F1, A}	80,00040		10.380,33	16.440,27	P_A	V _{Δyi}
β' _A	189,99500	240	213,84	108,96	1	0,02409829
t _{A, 1}	70,00030		10.594,20	16.549,26		0,03368009
β' ₁	252,99500	360	336,76	-127,25	2	0,03614743
t _{1,2}	123,00019		10.930,99	16.422,06		0,05052014
β' ₂	235,99500	420	252,18	-335,87	P_E	0,04217201
t _{2, E}	159,00009		11.183,21	16.086,25		0,05894016
β' _E	125,99500	Δ	802,88	-354,02		
t _{E, F2}	84,99998		802,78	-354,16	Δ'	
			0,10	0,14	f _y f _x	
W=	0,01958	f _s	0,18			
V _{β=}	0,00489	1020				
[β]=	802,88000		11.183,21	16.086,25		
tan t = Δy/Δx tan φ = Δx/Δy		t _{i+1} = t _i ± 200gon + β _i	V _{Δyi} = f _y / [s] · s _i		L = S _{A,E} · f _y · [ΔY] + f _x · [ΔX]	
Probe: t+φ= 100 bzw. 500gon		ΔY' = s · sin t	V _{Δxi} = f _x / [s] · s _i		[ΔY] ² + [ΔX] ²	
W = t _{E,F2} + n · 200gon - (t _{F1,A} + [β])		ΔX' = s · cos t				
V _β = W / n β _i = β _i ' + V _β		f _y = (y _E -y _A)-[ΔY']	y _i = y _{i+1} + Δy' _i +V _{Δyi}			
n= Anzahl der Brechpunkte einschl. Anfangs-und Endpunkt		f _x = (x _E -x _A)-[ΔX']	x _i = x _{i+1} + Δx' _i +V _{Δxi}		Q= S _{A,E} · f _y · [ΔX] - f _x · [ΔY]	
β _i ' =gemessener. Brechungswinkel		f _s = √(f _y ² +f _x ²)			[ΔY] ² + [ΔX] ²	