


Sensors + More



Pin Requirements IR sensor: TX, RX, VCC, GND	• •	• •	• • •		• •	• •	• •	• •	•
IR Sensor: TX, RX, VCC, GND			•	•					•
Laser Diode: VCC, GND, Digital	• •	•	• • •	•	• •				•
DC Motor Driver:	• •		• • •		• •	• •			
Stepper Driver:	• •		• • •	•		• •			
Servo Motor: PWM, VCC, GND	• •	• •	• • •	•	• •	• •		• •	•
LCD Screen:	• •	•	• • •	•	• •	• •		• •	•
	*	5	V .	4	Gr	OUY	nd:	Lev	JCV
Fuse Box	*	D	UCH	· ·	Tap	ė:	A	rduin	10
2 - Arduno	• •	• •	• • •		• •	• •	• •		
								• •	•
2 - DC Motors 3 - Servo Motor	• •	•	• • •	•	• •				•
-					• •	• •	• •	• •	•

