

# InfraGuard AI Inspection Report

Defect Count: 10

Crack Area Percentage: 10.22%

Severity: Medium

Risk Level: Monitor and Schedule Repair

Recommendation: Use Megapoxy Crack Injection System