
Absolute Error by Throughput - HSW
Mean Absolute Error (Cycles)
0
50
100
150
200
250
300
0
200
400
600
800
Measured Throughput (CPU Cycles)


Percentage Error by Throughput - HSW
Mean Absolute Percentage Error (%)
0
5
10
15
20
25
30
0
200
400
600
800
Measured Throughput (CPU Cycles)