HOMEWORK 0

Due date:

ALL: Thursday, Sept. 15

1- Have a look to "03 – OpAmps" and "04 – Noise", in the "04 - Supplementary Materials" folder in WeBeep. If you are familiar with this topics use the slide for a fast review, if you are not familiar with them try to fill the gap within the first weeks of the course, especially for the session "OpAmps". "Noise" will be discussed during the course and you will have time to learn something about it!

Due date:

SA: Monday, Sept. 19 SB: Wednesday, Sept 21

- 2- Install the NUCLEO environment, following "M 01 Installation guide", in the Laboratories folder. (Use the first option)
- 3- Verify the tool, following "M 02 First trial", in the "02 Laboratories" folder in WeBeep.

(for the course you don't need the "STM32CubeMX + Keil workflow")