







# AUTOMATION OF ENERGY SYSTEMS

Alberto Leva

13 February 2020

Reg. No. \_\_\_\_\_

Last name \_\_\_\_\_

Given name(s) \_\_\_\_\_

Signature \_\_\_\_\_

- Answer the questions in the spaces provided.
- If you run out of room for an answer, continue on the back of the page.
- Hand in *only* this booklet. No additional sheets will be accepted.
- Scoring also depends on clarity and order.

1. Consider an islanded electric generator, and let its transfer function – having as input the command  $\theta \in [0, 1]$  and as output the variation  $\Delta P_g$  of the generated power expressed in MW – be

$$G(s) = \frac{10}{1 + 2s}.$$

- (a) Assuming a network inertia of  $10k\text{J}/(\text{r/s})^2$ , determine the network equivalent time constant  $T_A$ .


Considering  $\omega_0 = 2\pi f_0$  with usually  $f_0 = 50\text{Hz}$ ,  $\omega_0 = 314.16 \text{ rad/s}$

$$T_A = \frac{J\omega_0^2}{P_m} \quad \text{with } P_m = 10 \text{ MW as we can see from } G(s)$$

$$= 98.7 \text{ sec}$$

- (b) Draw the block diagram representing the generator, the network and a primary plus secondary frequency controller in PI form.

$$\text{In PI form } C(s) = \frac{K_s}{s} + K_p = K \frac{1+sT_i}{sT_i}$$



- (c) Tune the controller for a settling time of 20s and determine the corresponding phase margin.

If we wanna obtain  $t_{SET} = 20s$ , we want

$$\omega_c = \frac{1}{\frac{20}{5}} = 0.25 \text{ rad/s}$$

We have the generator pole in  $0.5 = \omega_p$

We can place PI ZERO to obtain  $\varphi_m = 50^\circ$   
by placing properly:


$$T = 1/0.06 = 16.7 \quad \text{to guarantee } \varphi_m = 50^\circ$$

$$\mu = \tilde{\omega}^2 = 0.0164 \rightarrow$$

$$\mu \frac{1+sT}{s^2(1+sT)} = \frac{1+sT}{s} < \frac{1}{1+sT} \frac{1}{sT}$$

$$\Rightarrow K = \mu T = 1.42$$

$$K \frac{1+sT}{s} = k_i \frac{1+sT_i}{sT_i} \Rightarrow \begin{cases} \frac{k_i}{T_i} = K \rightarrow K_i = 23.73 \\ T_i = T = 16.7 \end{cases} \quad \begin{matrix} \text{PI} \\ \text{controller} \\ \text{parameters} \end{matrix}$$




2. Consider a thermal system in which a body of capacity  $C = 20 \text{ kJ}/\text{°C}$  is connected to two daisy-chained heaters (hereinafter H1 and H2). Both can be described by a first-order system with a  $[0, 1]$  command input, a gain of  $2\text{kW}$  and a time constant of  $5\text{s}$ , however the efficiencies of H1 and H2 (defined as power released to the body over consumed power) are respectively  $0.5$  and  $0.8$ . The body disperses heat through a thermal conductance  $G = 80\text{W}/\text{°C}$  toward an exogenous temperature  $T_e$ ,

- (a) Draw an electric equivalent of the system.


from the system equations

$$C \dot{T} = P_{H1} \eta_1 + P_{H2} \eta_2 - G(T - T_a)$$



$$\hookrightarrow T(s) = \frac{P_{H1} \eta_1 + P_{H2} \eta_2}{G(1 + s\frac{C}{G})} + \frac{T_a}{(1 + s\frac{C}{G})}$$

- (b) Draw a scheme to control the body temperature  $T$  with a single regulator, daisy-chaining the heaters in the correct order



In this way first we use  $H_2$  which has an higher efficiency and then  $H_1$

(c) Tune the regulator for a worst-case settling time of 30 minutes.

$$\text{tune for } t_{\text{SET}} = 30 \text{ min} \rightarrow \omega_c \approx \frac{1}{\frac{1800}{5}} = \frac{1}{360} \approx 0.0028 \text{ rad/s}$$

the actuators have a dynamic

in the order of  $1/5 = 0.2 \text{ rad/s}$  almost 2 decades

so we

tune  $C(s)$

on

after  $\omega_c$ , so we can  
neglect it when tuning  
(primarily a phase loss negligible!)

$$\frac{1}{G} \cdot \frac{1}{1+s \frac{\omega_c}{G}} = 0.0125 \frac{1}{1+s250} \Rightarrow \text{we want } L(s) \approx \frac{1}{360s}$$

set up

$$C(s) = \frac{1}{360s} \cdot \frac{1+250s}{0.0125} = \frac{1}{4.5s} (1+250s) \quad \text{PI control}$$

3. Illustrate the "turbine follows" control scheme for electric generators, indicating and briefly motivating its advantages and disadvantages.

looking to the internal control of the generator, so the specific control with input  $\delta_f, \delta_t$  value opening and output mech power and pressure energy  $P_m, e_m$ .

One possible control strategy to approach the simplified  $2 \times 2$  generator control scheme, named "turbine follows" uses  $\delta_t$  (throttling valve opening, controlling the fluid ent. eng. inside turbine) to control  $e_m$  (pressure energy of fluid) and  $\delta_f$  (fuel valve) to control  $P_m$  (mech power).

This allow for a perfect pressure control, so no mechanical stress on the turbine, BUT slowdown the mechanical power "reactivity", because an input  $\delta_f$  has to traverse through the slow thermal dynamics until having effect on  $P_m$ .

So it's a good solution when dealing with slow load variation

4. Explain, with the need of convenient schemes if you deem it useful, what is meant for "time division output" actuation, with particular reference to its use in the control of thermal systems.

time division output is a particular type of actuation scheme on which we simulate a modulating actuator using an on/off dynamic.

This is often useful for high power actuator hard to modulate or actuator more efficient if used on full power.

Knowing the process timescale, we select a sample time  $T_s$  enough smaller than it, on each actuation period  $T_s$  we maintain the actuation signal  $u \in [0,1]$  on for a fraction of time that define the seen action as a modulating one for the process!

↓

This is very useful for thermal systems, for example when we deal with huge pumps or other device that works better when on full range (?)