


Strain-coordinate design



Each marker is one prescribed macroscopic strain coordinate; no stress labels are shown.