



**Assembly Instructions** 


Robotic Arm

#### Material











top x1



wall\_front x1



bottom x1





adapteur x1



motor\_link\_xl x1



tree\_base x1



fixing\_base\_tree x1












adaptation SKF 2708 x1




4

motor link Screws : - M2 (12) x4




7

side front




2

top Screws : - M3 (20) x4




5

Screws : - M2 (12) x4




8

bottom big gear




3

tree fixing tree SKF 2708 x1 Screws: - M3 (20) x2





6

Small gear




5







tree\_shoulder x1





small\_gear\_shoulder (25 teeths) x1



big\_gear\_shoulder (110 teeths) x1




side x1



side\_2 x1






beag gear tree fixing tree




2

SKF 7202




3

left side right side Screws : - M5 (70) x3




4


motor small gear Screws : - M2 (12) x2




5

Screws : - M2 (12) x4









tree\_wrist x1



fixing\_hand x1



fixing\_camera x1





fixing\_rod x1



cover\_rod x1




finger x3




fixing\_AX



threaded\_rod x1







motor fixing ax Screws: - M2 (8) x4




2

fixing camera Screws : - M2 (10) x4



3

fixing hand tree




threaded rod nut



fixing rod cover rod



6 fixing finger



7


finger x3 Screws : - M2 (15) x6




8

Screws : - M5 (25) x3























big\_gear\_wrist (50 teeths) x1

radius x2

motor motor link Screws : - M2 (12) x4



SKF 7202 x2



5

Small gear Big gear





2


tree arm x1 Screws : - M2 (12) x4



arm x1 Screw : - M5 (60) x1




















big\_gear\_elbow (105 teeths) x1




humerus x2

motor motor link Screws: - M2 (12) x4




2

arm x1 Screws : - M2 (12) x4




3 SKF 7202



4

arm x1 Screws : - M5 (80) x1



5

small gear big gear

