

Ethernet Relay Board

Login: admin

Pass: gce.electronics



Step1: Plug the RJ45 to the board and your local network

Step2: Power on the board (connect the DC adaptor)


Step3: Exécute the Tools « scandevice.exe »

Step4: Click on Button « Discover Devices »



Step5: The IP address of the relayboard appears

Step6: Click directly on the line for connect to the board



Step7: Go to configuration menu if you want to change parameters.