


Fragment of a feedback circuit



Note:

1. The diagram is a reconstruction of a separate node. The positional designations of the components are entered for convenience of description and do not coincide with the marking of the components on the original board.
2. RV1, R7 — added during repair for DC offset adjustment.
3. C1 was missing from the board being repaired. Installed during the repair to ensure the stability of the node.