

ML Patched ALC AppleHDA

For Realtek ALC885 through ALC898 on board audio codecs

Requirements

- 1. Realtek ALC*, one of the following Device_IDs:
- *See Notes below for supported ALC codecs
- 1a. 10ec0885
- 1b. 10ec0887
- 1c. 10ec0888
- 1d. 10ec0889
- 1e. 10ec0892
- 1f. 10ec0898
- 2. Mountain Lion 10.8.4 or later
- 3. Supported Audio-IDs (Audio_ID = layout-id)
- 3a. Audio_ID: 1 5/6 port ALC898 onboard audio and AMD/Nvidia HDMI audio*
- 3b. Audio_ID: 2 3 port ALC898 onboard audio and AMD/Nvidia HDMI audio*
- 3c. Audio_ID: 3 3/5/6 port ALC898 onboard audio and HD3K/HD4K/AMD/Nvidia HDMI audio*

Audio_IDs: 1 and 2 support analog 5.1 surround sound, 3 does not

Audio_IDs: 1, 2 and 3 require HDMI audio dsdt edits for HDMI audio.

Configuration

Comgaration							
Device	Port	Location	Notes	Audio ID: 1	Audio ID: 2	Audio ID: 3	
1. Mic	Pink	Rear	1 & 2 Linked	Yes	Line Out (Center/Sub)	Yes	
2. Mic (LineIn)	Pink	Front	2 Mutes 1	Yes	Yes	Yes	
3. LineIn	Blue	Rear		Yes	LineOut (Rear)	Yes	
4. SPDIFIn	Yellow	Rear	Optional				
5. Speakers (Front)	Green	Rear	5 & 6 Linked	Yes	Yes	Yes	
6. Headphones	Green	Front	6 Mutes 5	Yes	Yes	Yes	
7. LineOut (Center/Sub)	Orange	Rear		Yes	Not Available	No	
8. LineOut (Rear)	Black	Rear		Yes	Not Available	Yes	
9. LineOut (Side)	Grey	Rear		Optional	Not Available	No	
10. SPDIFOut	Orange	Rear	Stereo/ DD/DTS	Yes	Yes	Yes	
11. HDMI		Rear	Edits Required	AMDNvidia	AMD/Nvidia	HD3K/ HD4K	

Patched ALC AppleHDA Enabling Techniques

1. No dsdt/audio enabler = Audio_ID, install either enabler (use 1a or 1b, not both)

1a. Audio_ID = 1, HDAEnabler1.kext

https://github.com/toleda/audio_HDAEnabler1 Download ZIP

1b. Audio_ID = 2, HDAEnabler2.kext

https://github.com/toleda/audio_HDAEnabler2 Download ZIP

- 2. dsdt/HDEF/layout-id = Audio ID, see [Guide] Add or Edit dsdt/HDEF.pdf
- 2a. Audio_ID = 1, 0x01, 0x00, 0x00, 0x00, 0x00
- 2b. Audio ID = 2, 0x02, 0x00, 0x00, 0x00, 0x00
- 2c. Audio ID = 3,0x03,0x00,0x00,0x00,0x00
- 3. Clover/Config.plist/PCI/HDAInjection
- 3a. Audio ID = 1, HDAInjection=1
- 3b. Audio ID = 2, HDAInjection=2
- 3c. Audio ID = 3, HDAInjection=3

No dsdt/HDEF?

See ML: How to Add or Edit dsdt/HDEF.pdf

Audio ID/layout-id Table

Audio ID	LayoutID	layout-id	dsdt layout-id Injection
(dec)	(dec)	(hex)	(hex)
1	1	1	0x01, 0x00, 0x00, 0x00
2	2	2	0x02, 0x00, 0x00, 0x00
3	3	3	0x03, 0x00, 0x00, 0x00

Speakers

- 1. Audio ID: 1 and 3, match connector color to same motherboard/case port color
- 2. Audio ID: 2 (3 port motherboard audio)
- a. Plug black connector into blue motherboard port for rear speakers
- b. Plug green connector into green motherboard port for front speakers
- c. Plug orange connector into pink motherboard port for center/sub speakers
- d. Front panel: Match connector color to same case port color

Audio Input Level Setting

- 1. Mic (Pink/Motherboard), Line In (Pink/Chassis) and Line In (Blue/Motherboard) levels are the same
- 2. Three Amplifiers
- a. Source (mic, player, etc.): set volume high
- b. OS X Input Amp (System Preferences/Sound/Input/device): set volume 50%
- c. OS X Output Amp (System Preferences/Sound/Output/device, keyboard): set volume to personal preference

Optional Installs

- 1, Configure 5.1 Surround Sound Aggregate Device (Not available with Audio ID: 3)
- a. Applications/Utilities/Audio MIDI Setup
- 2. Install Line In http://www.rogueamoeba.com/freebies/

Customization

See ML-Customizing the Patched AppleHDA.pdf

Notes

- 1. ALC can be:
- a. ALC885, 889a
- b. ALC887, 888b
- c. ALC888, 888s,
- d. ALC889
- e. ALC892
- f. ALC898

Kexts

1. AppleHDA_v2.3.7

- 1a. Audio ID: 1
- i. ALC on board 5/6 audio ports
- ii. HDMI audio AMD/Nvidia discrete graphics
- 1b. Audio ID: 2 (3 port motherboard audio)
- i. ALC on board 3 audio ports
- ii. HDMI audio AMD/Nvidia discrete graphics
- 1c. Audio ID: 3 (HD3K/HD4K HDMI audio only)
- i. ALC on board 3/5/6 audio ports
- ii. HDMI audio HD3K/HD4K integrated graphics
- iii. HDMI audio AMD/Nvidia discrete graphics

Troubleshooting

- 1. Shutdown/Pull power cord/Press power button twice/Wait 30 seconds/Plug power in/Boot
- 2. System Preferences/Sound/Output No Audio Devices
- a. Delete ALC8xxHDA, ALC8xx, 8xxHDAEnabler HDAEnabler... and any other audio enablers from S/L/E
- b. Verify 10ec 08xx (IOReg/AppleHDAControllerIOHDACodecDevice/IOHDACodecVendorID)
- c. Reinstall Reinstall MultiBeast/Audio/Realtek ALC8xx/
- 3. System Preferences/Sound/Output/Audio Devices present No Sound
- a. Check Mute
- b. Check Volume
- c. Reinstall MultiBeast/Audio/Realtek ALC8xx/
- 4. System Preferences/Sound/Input/Audio Devices present No Sound
- a. Check Mute
- b. Check Volume
- c. Reinstall MultiBeast/Audio/Realtek ALC8xx/
- 5. Center/Sub No sound
- a. Audio MIDI Setup/5.1 Surround Sound Aggregate Device/Configure Speakers
- b. Line In/Select Input/Select Output (5.1 Surround)/Select Pass Thru
- c. Verify Center/Sub working in Audio MIDI Setup
- 6. Internal Microphone/Line In No sound
- a. Audio MIDI Setup/5.1 Surround Sound Aggregate Device/Configure Speakers
- b. Line In/Select Input/Select Output (5.1 Surround)/Select Pass Thru
- c. Select a speaker in Audio MIDI Setup/verify test tone
- 7. Headphone static
- a. Check green front port connection (chassis)
- b. Check green rear port connection (motherboard)
- 8. Mic static
- a. Check pink front port connection (chassis)
- b. Check pink rear port connection (motherboard)

Credit

THe KiNG [HOW TO] Patch AppleHDA - Knowledge Base - Project OS X Forums VHC888 ALC889A, Gigabyte (Intel): now having a working front mic - InsanelyMac Forum :: ErmaC::: AppleHDA patching in Mountain Lion - Page 4 - Sound - InsanelyMac Forum PikeRAlpha

RevoGirl Not forgotten