HAZARDS	RISK BEFORE					RISK AFTER		
	Target	Severity	Probability	Risk code	COUNTERMEASURES	Severity	Probability	Risk code
Undetected intrusion due to sensors or contacts malfunctioning	R	II	С	3	Add redundant sensors and contacts in order to create many levels of protection	П	D	2
	Р	I	С	3		I	D	2
The system can not be activated due to a malfunctioning access system	R	П	С	3	Add redundant keypad or remote apps in order to allow the user to use different systems	П	D	2
	Р	I	С	3		I	D	2
Lack of power supply to Central unit	R	Ш	Α	3	Program phone calls that inform the user about the lack of power	III	С	1
	Р	IV	Α	2		IV	С	1
Missing telephone network	R	III	С	2	Equip the system with both GPS and a landline	III	D	1
	Р	IV	С	1		IV	D	1
Low battery level, shut down risk	R	Ш	В	3	Program phone calls that inform the user about low battery level	III	D	1
	Р	III	В	2		III	D	1