



Diamond · 50 cm · Headwind · Level 2


P1 / D1 · B11




P2 / D2 · B10




P3 / D3 · B13



P4 / D4 · B14



P5 / D5 · B12



Fit stages first, then calculate time

Each drone retains its own hovering record.

The initial unchanged-SOC period is removed.

Raw SOC stage slopes are fitted independently.

Rates are normalized with the existing battery baseline.

Full-reference stage time = SOC drop / stage rate.

— Measured SOC — Independent stage fits