Nios II Embedded Design Suite Release Notes

2014.12.15

RN-EDS





These release notes cover versions 13.0 through 14.1 of the Altera[®] Nios[®] II Embedded Design Suite (EDS). These release notes describe the revision history for the Nios II EDS.

For the most recent list of errata for the Nios II EDS, refer to the **Knowledge Base** page of the Altera website. Also, you can use the **Knowledge Base** to search for errata based on the product version affected and other criteria.

Related Information

Altera Knowledge Base

Product Revision History

The following table shows the revision history for the Nios II EDS.

Table 1: Nios II Embedded Design Suite Revision History

Version	Date	Description
14.1	December 2014	 Nios II Gen1 is now called Nios II Classic Nios II Gen2 is binary compatible with Nios II Classic Upgrade to Eclipse[®] 4.3 New embedded IP: HPS trace port interface unit (TPIU) Trace IP (Arria[®] 10 SoC) HPS gigabit media independent interface (GMII) to reduced gigabit media independent interface (RGMII) Adaptor HPS GMII to serial gigabit media independent interface (SGMII) Adaptor Nios II Toolchain Improvements: Link Time Optimization enabled [-flto] Upgrades: GCC v4.8.3, Newlib v1.18, GDB v7.7 Windows host compile/build time performance improvements -for example: three times faster to build webserver example

© 2014 Altera Corporation. All rights reserved. ALTERA, ARRIA, CYCLONE, ENPIRION, MAX, MEGACORE, NIOS, QUARTUS and STRATIX words and logos are trademarks of Altera Corporation and registered in the U.S. Patent and Trademark Office and in other countries. All other words and logos identified as trademarks or service marks are the property of their respective holders as described at www.altera.com/common/legal.html. Altera warrants performance of its semiconductor products to current specifications in accordance with Altera's standard warranty, but reserves the right to make changes to any products and services at any time without notice. Altera assumes no responsibility or liability arising out of the application or use of any information, product, or service described herein except as expressly agreed to in writing by Altera. Altera customers are advised to obtain the latest version of device specifications before relying on any published information and before placing orders for products or services.

ISO 9001:2008 Registered



Version	Date	Description
		 64-bit support for the remaining host tools: 64-bit nios2-gdb-server 64-bit nios2-flash-programmer 64-bit nios2-terminal Nios II Gen2 support for Max® 10: Altera user flash memory (UFM) MemInit for synthesis and simulation UFM Bootloader alt-file-convert (BETA) tool added Quad serial configuration (EPCQ) BootLoader and EPCQ HAL Support Upgraded EPCQ Controller IP (x4, L support)
14.0	July 2014	 Verified with Quartus II v14.0 software 32-bit host support removed Added support for Nios II Gen2 processor cores Resolved runtime stack checking issues Resolved compiler long jump support issue Resolved linking issue with newlib for Floating Point Hardware 2
13.1	November 2013	 Verified with the Quartus II software v13.1 GCC upgraded to v4.7.3 Enhancedfloating point custom instruction support ECC support Universal boot copier
13.0	May 2013	Verified with the Quartus II software v13.0

For more information about Nios II EDS features, refer to the *Nios II Processor Reference Handbook* and the *Nios II Software Developer's Handbook*.

Related Information

- Nios II Processor Reference Handbook
- Nios II Software Developer's Handbook

Nios II EDS v14.1 Updates

Nios II Gen2 Processor Core

The last version of the Nios II is 14.0 and it is named Nios II Classic. Nios II versions after this build are called Nios II Gen2.

The Nios II Gen2 processors are binary compatible with the Nios II Classic processors, but have the following new features:



- Options for a 64-bit address range
- Optional peripheral memory region
- Faster and more deterministic arithmetic instructions

New Embedded IPs for 14.1

The list of new IP includes:

• HPS Ethernet converter IPs - These allow you to assign the HPS Ethernet I/O pins to FPGA I/O pins and convert them from GMII format to RGMII or SGMII.

Note: This is very helpful if you are pin limited by the HPS I/O.

- New device family-specific IP cores:
 - Arria 10 TPIU trace IP. Trace is the ultimate tool in runtime software debug, much like Signaltap is for FPGA development. This IP enables developers to export the ARM[®] Cortex[™]-A9 trace debug signals to external pins so that trace debug modules like Lauterbach[®] or ARM Dstream, can be connected to the A10 SoC Cortex-A9.
 - Max 10 New IPs that deliver Qsys compatible interfaces to the Max10 ADCs and user flash. These new IPs are used in the Max10 example designs.

The 14.1 release has new example designs that demonstrate:

- Max 10 sleep mode, for low power applications
- Analog I/O for developers that want to use the integrated ADCs
- Dual configuration capability from the Max 10 on-chip configuration flash memory

The Cyclone[®] V and ArriaV SoC golden system reference designs (GSRDs) have also been updated to support the 14.1 ACDS and SoC EDS releases, this means that they will automatically include the SoC software fixes in 14.1 like the PLL workaround in the preloader.

64-Bit Host Support Enhanced

In this release, 64-bit capability was added to the following tools:

- 64-bit nios2-gdb-server
- 64-bit nios2-flash-programmer
- 64-bit nios2-terminal

Note: Within ACDS, at least two GDB servers and two flash programmers are shipped.

Upgrades to the Eclipse Environment

The Eclipse environment has been upgraded to version 4.3 to bring the benefits of the newer environment to the Nios II development suite.

There are command line option differences between GCC v4.8.3 and the previously supported version. If you have an existing project created with a previous version, you need to update your makefiles or regenerate your board support package (BSP).

The Free Software Foundation provides the downloads available under **GCC Download** and full GCC release notes are available under **GCC Releases**.

Related Information

http://gcc.gnu.org/



Upgrades to the Nios II GNU Toolchain

The following tools have been upgraded:

- GCC to version 4.8.3
- GDB to version 7.7
- NewLib to version 1.18

The build environment on the windows host platform has been optimized to give faster build times. For example, building the basic webserver application now takes one-third of the time it used to.

Additional Support for Max10

In this release, there is added support for Max10 through the addition of memory initialization and bootload support for the user flash memory.

There is a beta version of a new file conversion utility, called alt-file-convert, that makes it easier to get your data into the correct format for loading into flash.

Upgrades to the EPCQ IP Peripheral

HAL software and bootloader support for the upgraded EPCQ soft IP peripheral has been added.

The EPCQ IP core has finally been upgraded to add support for x4 mode and L devices, giving faster access to the EPCQ device from Nios or other FPGA based masters.

Nios II EDS v14.0 Updates

64-Bit Host Support

The Nios II Software Build Tools (SBT) v14.0 only supports 64-bit host systems.

Note: 32-bit hosts are no longer supported.

The following Nios II utilities have been moved to the Quartus II product:

- nios2-gdb-server
- nios2-flash-programmer
- nios2-terminal

Run-time Stack Checking

In earlier versions of the Nios II EDS, if run-time stack checking was enabled, the Nios II system could become unresponsive. This issue is resolved in v14.0.

Long Jump Support

In earlier versions of the Nios II EDS, the compiler did not correctly support long jumps (outside a 256-MB address range). This issue is resolved in v14.0.

Floating Point Hardware 2 Support

To fully support Floating Point Hardware 2, you must recompile the newlib C library. In the Nios II EDS v13.1, the linker failed to link the recompiled C library with the application. This issue is resolved in v14.0.

Qsys Bridge Support

Starting with v14.0, the Nios II EDS supports the Address Span Extender and IRQ Bridge cores.

Nios II Gen2 Processor Support

The Nios II Gen2 Processor Core

In v14.0, the Nios II processor core includes a preview implementation of the Nios II Gen2 processor core, supporting Altera's latest device families. The Nios II Gen2 processor core delivers size and performance similar to the original Nios II processor, and is compatible with Nios II Classic processor code at the binary level.

The tool flow and HAL include options to support Nios II Gen2 features. The workflow for generating BSPs and building software is the same, but BSPs generated for the Nios II Classic processor must be regenerated.

HAL Support for the Nios II Gen2 Processor

The Nios II Hardware Abstraction Layer (HAL) is extended to support the following Nios II Gen2 features:

- A 32-bit address range
- Peripheral (uncached) memory regions
- ECC protection on data cache and TCMs in the Nios II/f core

Nios II Gen2 Processor and MAX 10 FPGA Support

Nios II Gen2 Processor Cores and MAX 10 FPGA Support

MAX 10 FPGA devices are supported by the Nios II Gen2 processor, but not by the Nios II Classic processor. To implement a Nios II system on a MAX 10 device, you must use the Nios II Gen2 processor core.

The Altera On-chip Flash memory component, introduced in 14.0, enables Avalon-MM access to on-chip MAX 10 user flash memory. With this component, the Nios II boot copier can copy code to RAM from the MAX 10 user flash memory.

Tool Support for the MAX 10 FPGA

The HAL adds basic driver support for the MAX 10 analog to digital (A/D) converter.

The Altera device programming utilities are updated to support programming the MAX 10 user flash memory.

What's New in v14.0a10: the Nios II Gen2 Processor and Arria 10 FPGA Support

Arria 10 FPGA devices are supported by the Nios II Gen2 processor, but not by the classic Nios II processor. To implement a Nios II system on an Arria 10 device, you must use the Nios II Gen2 processor core.

Nios II EDS v13.1 Updates

GCC Upgraded to 4.7.3

In v13.1, the Nios II Software Build Tools (SBT) have been updated to support the v4.7.3 version of GCC.

There are command line option differences between GCC v4.7.3 and the previously supported version. If you have an existing project created with a previous version, you need to update your makefiles or regenerate your board support package (BSP).

Note: GCC v4.7.3 adds several new warnings and messages. If you used the -werror command-line option in the previous version, you might see unexpected errors generated by the new warnings.

For details about the Nios II GCC 4.7.3 implementation, refer to **Nios II GNU toolchain upgrade from GCC 4.1.2 to GCC 4.7.3** in the Altera **Knowledge Base**.

The Free Software Foundation provides a guide to porting to GCC 4.7, documenting common issues. This guide can be found on **GCC**, **the GNU Compiler Collection**, under **Porting to GCC 4.7**. Full GCC release notes are available under **GCC Releases**.

Related Information

- Altera Knowledge Base
- http://gcc.gnu.org/

Enhanced Floating Point Custom Instruction Support

In v13.1, Qsys adds an option to select a new floating point custom instruction set component, Floating Point Hardware 2.

To take advantage of software support for the Floating Point Hardware 2 instructions, include altera_nios_custom_instr_floating_point_2.h, which forces GCC to call newlib math functions (rather than GCC built-in math functions). Altera recommends that you recompile newlib with for optimum performance.

Note: Do not use the <code>-mcustom -fpu-cfg</code> command-line option for GCC. This option does not support the Floating Point Hardware 2 instructions.

The Nios II software build tools (SBT) add individual -mcustom commands to the makefile to support the Floating Point Hardware 2 custom instructions.

ECC Support

Starting in v13.1, the Nios II Processor parameter editor lets you enable ECC protection for the RAMs in the processor core and the instruction cache.

By default, ECC is not enabled on reset. Therefore, software must enable ECC protection. Software can also inject ECC errors into RAM data bits to support testing of the ECC exception handler and event bus.

The Nios II Hardware Abstraction Layer (HAL) is extended to support ECC initialization and exception handling.



Universal Boot Copier

In v13.1, the Nios II boot copier is upgraded to support more types of flash devices.

The upgraded boot copier is called the universal boot copier.

The Nios II boot copier copies the application binaries from flash devices to volatile memory. The flash memory is laid out with the FPGA image at the lowest memory address, followed by the Nios II application binary images.

In previous product releases, the FPGA image size was fixed for each device family. However, for devices in the Cyclone V, Stratix V, and Arria V families, the image size varies depending on the following variables:

- Flash type: Quad-output (EPCQ) or single-output (EPCS) Enhanced Programmable Configuration device
- Flash device capacity: 128 or 256 Mbits
- Compression
- Serial peripheral interface (SPI) configuration: ×1 or ×4
- Device layout: single or cascaded

It is difficult for the boot copier to identify the current combination so that it can use the appropriate image size, and any algorithm might fail to support future configurations.

To solve this problem, a header is added to the FPGA image to specify the image size. By using the image size from the header, the universal boot copier can work with any flash configuration in current or future devices.

The **sof2flash** utility is updated to support the universal boot copier.

This change does not impact to the ability of the FPGA control block to automatically program the FPGA image at power-on.

Known Issues and Errata

The following list contains known issues and errata, if any:

• There is a minor difference in the Nios II Gen2 processor cache behavior that might affect developers who choose to leverage the non-standard cache behavior of the classic processors in their applications.

Related Information

Altera Knowledge Base

For more information about known issues and erratas and how to work around it, search for "Nios II Gen2" on Altera Knowledge Base.

