Voids play different roles according to their:

- · position
- size

Two Phase Ti-Al Alloy

 α phase γ phase







