

## **Detailed Certificate of Calibration**

Mr. William Zhang

Shanghai, 200331

william@f-young.com

**CHINA** 

**Customer Information** 

Shanghai Forever Young Imp. & Exp. Co., Ltd.

Rm.105,107 of South Dianxin Building,

Tongji University, No.500, Zhennan Road

**Equipment Calibrated** 

Description: Six-Axis Force/Torque Sensor

Manufacturer: ATI Industrial Automation

Serial Number: FT18231 Model: Mini45 Calibration: SI-145-5 Electronics: DAQ Output Range:  $\pm 5V$ 

Gain Multiplier: 100%

Equipment Condition and Notes: Factory new.

Calibration Results: Passed

Offset: Normal Gain: Normal

Calibrated Ranges (±):

Fx	Fy	Fz	Tx	Ту	Tz
145 N	145 N	290 N	5 N-m	5 N-m	5 N-m

Measurement Uncertainty (95% confidence level, percent of full-scale load):

Fx	Fy	Fz	Tx	Ту	Tz
1.25%	1.00%	0.75%	1.25%	1.50%	1.25%

The above Measurement Uncertainty values are the maximum amount of error for each axis expressed as a percentage of its full-scale load.

Calibration Temperature: 22.2°±1.1° C (72°±2° F)

Temperature Compensation: hardware

Calibration Method: WI-FTP-026, DAQ Calibration Instructions

Date of Calibration: 01 Feb 2016

Certificate Date: 01 Feb 2016

Calibrated by: Melvin Wells, Calibration Technician

> Page 1 of 6 Certificate Number: FT18231-20160201

El E. Hell



This calibration is traceable to the National Institute of Standards and Technology (NIST).

ATI Industrial Automation (ATI) certifies that the above product was calibrated in accordance with applicable ATI procedures. These procedures are compliant with the ISO 9001 standard to ensure that the above product is within ATI specifications. To meet this level of accuracy any loads must be correctly aligned to the transducer origin and the transducer must be mounted to a sufficiently strong surface.

To ensure the transducer measurement uncertainties listed on page 1 are met, more-conservative limits are used as calibration targets during the calibration process. If any of the calibration targets are exceeded the calibration will not pass. It is possible for a transducer to exceed these calibration targets while meeting the page 1 measurement uncertainties. The following calibration targets were used for this transducer: Fx=1.00%, Fy=0.75%, Fz=0.50%, Tx=1.00%, Ty=1.25%, and Tz=1.00%.

Note: If this is a recalibration of a legacy transducer that does not have precision locating features (such as dowel holes), there could be additional error in Tx and Ty due to inexact mounting location. Precision locating features are highly recommended for best accuracy and can be added by ATI.

This certificate shall not be reproduced except in full without written approval from ATI. This certificate only applies to the items listed and does not include unlisted ancillary items such as data acquisition equipment.

For questions or comments, please contact your ATI representative.



## Calibration Accuracy Section Sensor System FT18231, Mini45/SI-145-5 Force units: N; Torque units: N-m

Calibrated Ranges (±)							
Fx	Fy	Fz	Tx	Ту	Tz		
145	145	290	5	5	5		

	Applied Loads						
	Fx	Fy	Fz	Tx	Ту	Tz	
1	0.000	40.034	0.000	-4.069	0.000	0.000	
2	-40.034	0.000	0.000	0.000	-4.069	0.000	
3	0.000	-40.034	0.000	4.069	0.000	0.000	
4	40.034	0.000	0.000	0.000	4.069	0.000	
5	0.000	120.102	0.000	-3.655	0.000	0.000	
6	-120.102	0.000	0.000	0.000	-3.655	0.000	
7	0.000	-120.102	0.000	3.655	0.000	0.000	
8	120.102	0.000	0.000	0.000	3.655	0.000	
9	0.000	35.586	0.000	-0.271	0.000	-4.072	
10	0.000	35.586	0.000	-0.271	0.000	4.071	
11	-35.586	0.000	0.000	0.000	-0.271	-4.071	
12	-35.586	0.000	0.000	0.000	-0.271	4.071	
13	0.000	-35.586	0.000	0.271	0.000	-4.071	
14	0.000	-35.586	0.000	0.271	0.000	4.072	
15	35.586	0.000	0.000	0.000	0.271	-4.071	
16	35.586	0.000	0.000	0.000	0.271	4.071	
17	0.000	0.000	57.827	-4.409	0.000	0.000	
18	0.000	0.000	57.827	0.000	-4.406	0.000	
19	0.000	0.000	57.827	4.409	0.000	0.000	
20	0.000	0.000	57.827	0.000	4.410	0.000	
21	0.000	0.000	222.411	0.000	0.000	0.000	
22	0.000	0.000	-222.411	0.000	0.000	0.000	
23	0.000	0.000	-57.827	4.409	0.000	0.000	
24	0.000	0.000	-57.827	0.000	4.406	0.000	
25	0.000	0.000	-57.827	-4.409	0.000	0.000	
26	0.000	0.000	-57.827	0.000	-4.410	0.000	

Refer to page 6 for important information on regarding this report.



	Full-Scale Error						
	Fx	Fy	Fz	Tx	Ту	Tz	
1	-0.21%	-0.03%	0.06%	-0.06%	0.29%	0.10%	
2	0.26%	0.12%	-0.02%	-0.18%	-0.29%	-0.21%	
3	-0.16%	0.02%	0.04%	0.06%	0.13%	-0.03%	
4	0.23%	0.08%	-0.09%	0.16%	-0.36%	0.02%	
5	-0.13%	0.11%	0.04%	0.18%	0.36%	0.03%	
6	0.28%	0.06%	0.09%	-0.16%	-0.16%	0.04%	
7	-0.16%	0.05%	0.06%	-0.03%	0.35%	0.05%	
8	0.30%	0.08%	0.08%	-0.28%	-0.41%	0.08%	
9	0.02%	-0.02%	0.02%	-0.20%	-0.01%	-0.02%	
10	-0.12%	-0.10%	0.05%	-0.24%	-0.04%	0.05%	
11	-0.01%	-0.05%	-0.01%	-0.07%	-0.07%	0.13%	
12	0.00%	-0.01%	-0.02%	0.05%	-0.41%	0.16%	
13	-0.08%	0.05%	0.00%	0.13%	-0.12%	0.10%	
14	0.01%	-0.02%	0.01%	0.01%	0.28%	-0.01%	
15	-0.05%	-0.09%	0.05%	-0.02%	0.24%	-0.04%	
16	-0.02%	0.01%	0.01%	0.02%	0.22%	-0.04%	
17	-0.09%	0.07%	-0.03%	-0.04%	0.27%	0.16%	
18	0.00%	0.06%	-0.05%	-0.14%	-0.22%	-0.10%	
19	-0.09%	0.04%	0.02%	0.00%	0.33%	-0.08%	
20	0.08%	0.05%	-0.02%	-0.33%	-0.18%	-0.03%	
21	0.13%	0.00%	0.03%	-0.01%	-0.02%	-0.07%	
22	-0.05%	0.06%	0.03%	-0.09%	-0.02%	-0.10%	
23	-0.08%	0.13%	-0.07%	0.05%	0.39%	0.13%	
24	0.34%	-0.10%	0.02%	-0.18%	-0.18%	-0.08%	
25	-0.07%	0.11%	-0.03%	0.06%	0.32%	-0.21%	
26	0.39%	-0.14%	-0.01%	-0.14%	-0.33%	0.20%	

Refer to page 6 for important information on regarding this report.

	Offset Report						
	Fx	Fy	Fz	Tx	Ту	Tz	
F/T Offset	0.1729	-0.3529	-2.2832	-0.0213	-0.0183	-0.0546	
	SG0	SG1	SG2	SG3	SG4	SG5	
SG Offset	0.0224	0.0222	0.0002	0.0261	0.0177	0.0295	
±SG Limit	0.2442	0.2442	0.2442	0.2442	0.2442	0.2442	

Offsets are measured in a unique configuration not available to the user.

Refer to page 6 for important information on regarding this report.



	Gain-Check Report					
	SG0	SG1	SG2	SG3	SG4	SG5
Lower Limit	0.7500	0.7500	0.7500	0.7500	0.7500	0.7500
Lower Output	0.9094	0.8640	0.8804	0.8485	0.8605	0.8444
Upper Output	0.9320	0.8726	0.8867	0.8569	0.8822	0.8638
Upper Limit	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000

Gain readings are measured in a unique loading configuration. Refer to page 6 for important information on regarding this report.



As part of our commitment to quality, each ATI force/torque transducer undergoes rigorous accuracy testing. This process, which involves applying and verifying a rich set of loading cases designed to cover the transducer's entire six-axis calibrated range, is designed to ensure that your transducer meets the measurement uncertainties listed in this Certificate of Calibration.

Our transducers often exceed our quality standards for accuracy. Often, transducers perform exceptionally well in certain loading situations. This report summarizes the performance of your ATI F/T transducer in our factory tests. It can be thought of as a 'best-case scenario' snapshot of your transducer's performance under laboratory conditions, in a variety of loading situations. You can expect the accuracy of your transducer measurements to fall somewhere between its performance during testing and the measurement uncertainties listed on its calibration certificate.

The Calibration Accuracy Section contains several tables of data. The Calibrated Ranges (±) table lists the transducer's rated range for each axis. The Applied Loads table lists the loads applied during calibration and testing. The Full-Scale Error table shows the sensor system's measurement error as a percentage of full scale for each axis in each loading case. The Offset Report table shows transducer readings during offset adjustment and associated control limits. And the Gain-Check Report table shows verification of the transducer's sensitivity and associated control limits. If included, the Before and After Report table shows a loading case relating the transducer's performance as received to its performance after recalibration.

For best accuracy, be sure to use your transducer's precision location features, and mount your transducer to a stiff surface. If an ongoing guarantee of sensor accuracy is important to you, we recommend that your sensor be tested annually. Contact your ATI Industrial Automation distributor to schedule recalibrations.