## Milinis Panel Paint & Towing

ABN 40976305544
5 Murray Street
Panel & Rust Repairs PO Box 275

Windscreens

Invoice Date 13/02/2017 **Estimate Number** 37

37896

Tully, Queensland, 4854 Ph 07 40682747 Fax 07 40683866 Spray Booth Private & Insurance Work Digital Images Available

Tax Invoice No

29960

e mail info@milinis.net

Invoice to: SHANNONS	Driver/Contact Excess Claim No Policy No Ouoted Bv Assessor	TBA M031557841 Robbie Milini Scott.Chapman - 0455 073 0455 073 583	
Vehicle: Toyota Landcruiser 80 4door Automatic Colour: BLUE Rego: 164RQI Odometer 346060 Mth/Yr Chassis/VIN JT711TJ8208102370	Date Started  Date Completed	15/11/2016 13/02/2017	
Customer Details Cameron Gardiner			
Remove & Replace		Hrs/Qty	<u>Value</u>
Snorkel			50.00
RH inner wheel arch fitting to remove snorkle			30.00
RHF Flare & Da			30.00
RH Fender Fttings			12.50
RH Fender Mould & reback			25.00
RHR Door Fittings			60.00
RHR Door Mould & reback			30.00
RHR Door Flare			30.00
RH Side Step & da			45.00
RHR Shockie			18.50
R & R Section	Total		\$331.00
Repair			
Firbe glass repair rh fender flare			240.00
RHR Door			80.00
Repair Section	Total		\$320.00
Paint - Metallic 2			
RHF Door Flare			110.00
RHR Door			165.00
RHR Door Flare			110.00
Blend rhr quarter panel flare			60.00
Mix and Match			25.00
Booth Allowance			25.00

		Hrs/Qty	<u>Value</u>
Metallio	e 2 Section Total		\$495.00
Parts	Part No		
RHF MUDFLAP	7660360011	1.00	103.95
RHF MUDFLAP CLIPS	9018906196	3.00	5.40
RHR DOOR FLARE	6106160903	1.00	227.22
RHR DOOR FLARE SEAL	6178360071	1.00	25.94
RH SIDE STEP	5108360020	1.00	233.33
RH SIDE STEP BRACKETS	5107960040	1.00	77.51
RH SIDE STEP END CAPS	5177360050	1.00	90.64
RH REAR MUDFLAP	UNI28.5	1.00	60.00
RHR SHOCKIE RIDEPRO	ZS117071	1.00	175.00
COVER SIDE DOOR	5177960050	1.00	83.29
Parts Se	ection Total	12.00	\$1,082.28
Fotal Original Estimate		28.00	\$2,228.28
Additional Estimate No 1			
Freight			
freight (for Shockie)		1.00	14.55
FREIGHT (downtown toyota)		1.00	57.71
FREIGHT	FREIGHT	1.00	40.00
	ion Total	3.00	\$112.26
Remove & Replace			
RHR coil spring			50.00
R & R &	Section Total		\$50.00
Parts	Part No		
RHR DOOR FLARE BRACKETS	6168360010	1.00	16.17
BRACKET RR WHEEL	6169560030	1.00	13.36
RHR COIL SPRING	ZC7565	1.00	155.25
RHR SHOCKIE RIDEPRO PRICE CORRECTION	ZS117071	1.00	-55.83
Parts So	ection Total	4.00	\$128.95
Total Additional Estimate 1		8.00	\$291.21
	Total		\$2,519.49
	GST		\$251.95
Job Total incl GST  Total Payable by Insurance Co			\$2,771.44
			\$2,771.44
	(Including \$251.95 GST)		. ,

N:\EQ32\Reports\quote.rpt Page 2 of 2