


1. UP PULLEY
2.DOWN PULLEY
3.SPRING SETS
4.MAJOR CASE
5.MACHINE COVER
6.PROTECT PLATE
7.PROTECT PLATE HANDLE
8.OPERATION TABLE
9.OPERATION TABLE SHELF
10.DOWN SAW PROTECTER
11.UP SAW PROTECTER
12.TRIANGULAR SHELF
13.DOOR SHAFT PARTS
14.SHORT FLAT STRIP
15.DOOR LOCK STRIP
16.NUTS
17.PULLEY SHAFT
18.SMALL FIXING PARTS
19.UP AND DOWN COVER
20.GUIDE SETS
21.ORBIT FIXING SETS
22.ADJUSTING PLATE
23.LOCK SCREW
24.SLIDE BAR
25.PULLEY FIXING PARTS
26.BEARING COVER
27.NYLON ROD
28.MOTOR
29.INSIDE LOCK SPRING
30.OUTSIDE LOCK SPRING
31ADJUSTING SCREW
32.SPRING
33.GASKET
34.INNER HEXAGON SCREW
35.M6 SCREW
36.PHILLIPS SCREW
37.PULLEY SCREW

技术要求

1. 装配到位，螺钉拧紧，不得有松动，轴承转动自如，不得出现卡死现象;

2. 机器表面无伤痕。