

Act of inspection - Block B, 3rd floor

Ventilation mounting: design documents missing.