

Device Inventory Report

All registered PLC/IoT devices

REPORTING PERIOD
01/01/2025 – 18/02/2026

Generated: 18/02/2026

1 Device Inventory Report

Name	Protocol	Status	Port	Latency (ms)	Auto Reconnect	Last Error
MFM 20	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
Lighting	modbus	Connected	502	21.0	1	
MFM 10	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
Nexsine Production	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 3	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 11	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
PLC 1	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 4	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
Nexsine Incomer	modbus	Connected	502	16.0	1	
MFM 12	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
Modbus Device TEST	modbus	Connected	5020	16.0	1	
Server 1	opcua	Reconnecting	4840	0.0	1	[Errno -2] Name or service not known
MFM 5	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 13	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 17	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
SN Production	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 6	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
Device 1	modbus	Connected	5020	38.0	1	
MFM 14	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
SN Incomer	modbus	Connected	502	33.0	1	
MFM 18	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED

Name	Protocol	Status	Port	Latency (ms)	Auto Reconnect	Last Error
MFM 7	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
Spare	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 15	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 19	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 8	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
APFC Incomer	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 16	modbus	Reconnecting	502	0.0	1	
MFM 2	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 9	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
Busduct Testing Machine	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED
MFM 1	modbus	Reconnecting	502	0.0	1	TCP_CONNECT_FAILED

Device Inventory Report — Confidential

Period: 01/01/2025 – 18/02/2026 | Generated: 18/02/2026