




- 1. Table of Contents (This Page) Created on Sun Feb 15 16:48:41 2015
- 2. component
- 3. solder
- 4. outline
- 5. plated-drill
- 6. componentmask
- 7. soldermask
- 8. topsilk
- 9. bottomsilk
- 10. toppaste
- 11. topassembly
- 12. bottomassembly
- 13. fab
































| There are 3 different drill sizes used in this layout, 99 hales total | Symbol | Diam. (Inch) | Count | Plated? | | Fabrication Drawing | Fabrication Dr



Board outline is the centerline of this path