## YellowHat Assembly and Testing

## Pre-assembly work

- 1. Burn bootloader using Arduino as ISP, Arduino Nano, old bootloader
- 2. Burn software using FTDI with AVR ISP for Arduino Nano and old bootloader

## Assembly

- 1. Install SMT RGB LED on the bottom or component side of the board
- 2. Install Stick connector on top side
- 3. Install LED Pigtail. Squared hole (Pin1) is GND (White wire) on top side
- 4. Install 12pol pin headers A, B, C, D on top side
- 5. Install DC barrel connector on top side

## **Testing**

- 1. Install Stick, set to Loconet over TCP with settings for LED and buttons
- 2. Connect LED Matrix
- 3. Connect power
- 4. Verify Stick is booting up
- 5. Check input buttons with shorted pin header,
- 6. Issue switch commands, verify Matrix LED